

CUSTOMER #:

124670D

Bruce Chevrolet Buick GMC Limited

398 Highway 303, RR#2, Digby, NS B0V 1A0

Tel: 902-245-2541 · Fax: 902-245-5157

Toll Free: 1-800-565-3396

www.brucegm.com

customerservice@bruceautogroup.com

INTERNAL

PAGE 1

HOME: CONT:N/A

BUS: CELL: SERVICE ADVISOR: 923 COREY ONEIL

COLOUR	YEAR	MAKE/MODEL	VIN	LICENSE	ODOMETER IN/OUT	TAG
DARK BLUE	10	CHEVROLET SILVERADO	1GCPKPEX2AZ133816		149779/149779	T3816

DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
DD			18:00 07MAR18		99.95	CASH	09MAR18

R.O. OPENED READY OPTIONS: STK:GD18147A TRN:A 13)JAN.-2013/

10:33 06MAR18 13:15 09MAR18

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

A MOTOR VEHICLE INSPECTION							
MVI MOTOR VEHICLE INSPECTION							
	903	IUT	0.50			29.15	29.15
PARTS:	0.00	LABOR:	29.15	OTHER:	0.00	TOTAL LINE A:	29.15
149779 see large list attached to the RO							
*****							

B** INTERNAL GOLD RECON							
80GMZZ102 INTERNAL GOLD RECON							
	941	ISUT	5.00			150.00	150.00
PARTS:	0.00	LABOR:	150.00	OTHER:	0.00	TOTAL LINE B:	150.00
149779 Internal gold complete							
*****							

C** PICTURES TAKEN AND UPLOADED							
CAUSE: TAKE PICTURES AND UPLOAD							
PICTURES PICTURES TAKEN AND UPLOADED							
	941	ISUT	0.30			19.95	19.95
PARTS:	0.00	LABOR:	19.95	OTHER:	0.00	TOTAL LINE C:	19.95
149779 Pictures taken and uploaded							
*****							

D** PLEASE REPAIR POWER STEERING HIGH PRESSURE LINE							
CAUSE: power steering							
REPAIR1 Please repair:							
	906	IUT	0.80			88.99	88.99
	1	CQ624205	HOSE		258.23	258.23	258.23
	2	19329449	\$FLUID		20.07	20.07	40.14
PARTS:	298.37	LABOR:	88.99	OTHER:	0.00	TOTAL LINE D:	387.36
149779 power steering replaced power steering lines and added fluid- 906							
*****							

E** PLEASE REPAIR DRIVE BELT							
REPAIR1 Please repair:							
	903	IUT	0.30			25.99	25.99
	1	CQ506960	BELT		112.42	77.53	77.53
PARTS:	77.53	LABOR:	25.99	OTHER:	0.00	TOTAL LINE E:	103.52

ON BEHALF OF SERVICING DEALER, I HEREBY CERTIFY THAT THE INFORMATION CONTAINED HEREON IS ACCURATE UNLESS OTHERWISE SHOWN. SERVICES DESCRIBED WERE PERFORMED AT NO CHARGE TO OWNER. THERE WAS NO INDICATION FROM THE APPEARANCE OF THE VEHICLE OR OTHERWISE, THAT ANY PART REPAIRED OR REPLACED UNDER THIS CLAIM HAD BEEN CONNECTED IN ANY WAY WITH ANY ACCIDENT, NEGLIGENCE OR MISUSE. RECORDS SUPPORTING THIS CLAIM ARE AVAILABLE FOR (1) YEAR FROM THE DATE OF PAYMENT NOTIFICATION AT THE SERVICING DEALER FOR INSPECTION BY MANUFACTURER'S REPRESENTATIVE.	STATEMENT OF DISCLAIMER	DESCRIPTION	TOTALS	
	The factory warranty constitutes all of the warranties with respect to the sale of this item/items. The Seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.	LABOUR AMOUNT		
		PARTS AMOUNT		
		GAS, OIL, LUBE		
		SUBLET AMOUNT		
		MISC. CHARGES		
		TOTAL CHARGES		
		LESS DEDUCTIBLE		
		G.S.T. / P.S.T.		
		(SIGNED) DEALER, GENERAL MANAGER OR AUTHORIZED PERSON (DATE)	CUSTOMER SIGNATURE	PLEASE PAY THIS AMOUNT

HST: 10066 9050 RT0001

INTERNAL COPY

CUSTOMER #:

124670D

Bruce Chevrolet Buick GMC Limited

398 Highway 303, RR#2, Digby, NS B0V 1A0

Tel: 902-245-2541 · Fax: 902-245-5157

Toll Free: 1-800-565-3396

www.brucegm.com

customerservice@bruceautogroup.com

INTERNAL

PAGE 2

HOME: CONT:N/A

BUS: CELL: SERVICE ADVISOR: 923 COREY ONEIL

COLOUR	YEAR	MAKE/MODEL	VIN	LICENSE	ODOMETER IN/OUT	TAG
DARK BLUE	10	CHEVROLET SILVERADO	1GCPKPEX2AZ133816		149779/149779	T3816

DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
DD			18:00 07MAR18		99.95	CASH	09MAR18

R.O. OPENED READY OPTIONS: STK:GD18147A TRN:A 13)JAN.-2013/

10:33 06MAR18 13:15 09MAR18

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

149779 replaced the serpentine belt  
\*\*\*\*\*

F\*\* PLEASE REPAIR BOTH FRONT UPPER BALL JOINTS

REPAIR1 Please repair:

903 IUT 2.10 229.88 229.88

1 25812725 ARM 337.46 109.33 109.33

1 25812726 ARM 337.46 109.33 109.33

1 19209396 STUD KIT 132.96 132.96 132.96

4 11612278 NUT 10.06 10.06 40.24

4 15654866 BOLT 11.48 11.48 45.92

8 15741217 CAM 14.32 14.32 114.56

PARTS: 552.34 LABOR: 229.88 OTHER: 0.00 TOTAL LINE F: 782.22

149779 replaced both front upper control arms  
\*\*\*\*\*

G\*\* PLEASE REPAIR MIRROR ASSEMBLY FROMT BRINTONS

CAUSE: install mirrior

REPAIR1 Please repair:

906 IUT 0.70 75.99 75.99

1 BRINTONMIRROR MIRRRIOR ASSEMBLY 189.00 189.00 189.00

PARTS: 189.00 LABOR: 75.99 OTHER: 0.00 TOTAL LINE G: 264.99

149779 install mirrior removed door card and replaced broken driver side mirror - 906  
\*\*\*\*\*

H\*\* PLEASE REMOVE RUNNING BOARDWS

REPAIR1 Please repair:

903 IUT 0.50 55.99 55.99

PARTS: 0.00 LABOR: 55.99 OTHER: 0.00 TOTAL LINE H: 55.99

149779 removed both running boards  
\*\*\*\*\*

I\*\* MOUNT AND BALANCE TIRES - SET PRESSURES - TWO TIRES

CAUSE: tires

1003-2 MOUNT AND BALANCE TIRES - SET PRESSURES -

TWO TIRES

906 INT 0.60 39.95 39.95

ON BEHALF OF SERVICING DEALER, I HEREBY CERTIFY THAT THE INFORMATION CONTAINED HEREON IS ACCURATE UNLESS OTHERWISE SHOWN. SERVICES DESCRIBED WERE PERFORMED AT NO CHARGE TO OWNER. THERE WAS NO INDICATION FROM THE APPEARANCE OF THE VEHICLE OR OTHERWISE, THAT ANY PART REPAIRED OR REPLACED UNDER THIS CLAIM HAD BEEN CONNECTED IN ANY WAY WITH ANY ACCIDENT, NEGLIGENCE OR MISUSE. RECORDS SUPPORTING THIS CLAIM ARE AVAILABLE FOR (1) YEAR FROM THE DATE OF PAYMENT NOTIFICATION AT THE SERVICING DEALER FOR INSPECTION BY MANUFACTURER'S REPRESENTATIVE.	STATEMENT OF DISCLAIMER	DESCRIPTION	TOTALS	
	(SIGNED) DEALER, GENERAL MANAGER OR AUTHORIZED PERSON (DATE)	The factory warranty constitutes all of the warranties with respect to the sale of this item/items. The Seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.	LABOUR AMOUNT	
			PARTS AMOUNT	
			GAS, OIL, LUBE	
			SUBLET AMOUNT	
			MISC. CHARGES	
			TOTAL CHARGES	
			LESS DEDUCTIBLE	
			G.S.T. / P.S.T.	
			CUSTOMER SIGNATURE	PLEASE PAY THIS AMOUNT

HST: 10066 9050 RT0001

INTERNAL COPY

CUSTOMER #:

124670D

Bruce Chevrolet Buick GMC Limited

398 Highway 303, RR#2, Digby, NS B0V 1A0

Tel: 902-245-2541 Fax: 902-245-5157

Toll Free: 1-800-565-3396

www.brucegm.com

customerservice@bruceautogroup.com

INTERNAL

PAGE 3

HOME: CONT:N/A

BUS: CELL: SERVICE ADVISOR: 923 COREY ONEIL

COLOUR	YEAR	MAKE/MODEL	VIN	LICENSE	ODOMETER IN/OUT	TAG
DARK BLUE	10	CHEVROLET SILVERADO	1GCPKPEX2AZ133816		149779/149779	T3816

DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
DD			18:00 07MAR18		99.95	CASH	09MAR18

R.O. OPENED READY OPTIONS: STK:GD18147A TRN:A 13)JAN.-2013/

10:33 06MAR18 13:15 09MAR18

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

2 2457017 TIRES2457017 130.00 130.00 260.00

PARTS: 260.00 LABOR: 39.95 OTHER: 0.00 TOTAL LINE I: 299.95

149779 tires mount and balanced two tires- 906

\*\*\*\*\*

J\*\* PLEASE REPAIR: FIX FRAME

REPAIR1 Please repair:

903 IUT 7.00 805.88 805.88

10 10% OFF SERVICE SALES -80.59 -80.59

1 10952414 PROTECTOR 15.66 15.66 15.66

PARTS: 15.66 LABOR: 805.88 OTHER: -80.59 TOTAL LINE J: 740.95

149779 repaired frame

\*\*\*\*\*

K\*\* PLEASE REPAIR LOWER BALL JOINT

REPAIR1 Please repair:

903 IUT 2.20 245.99 245.99

PARTS: 0.00 LABOR: 245.99 OTHER: 0.00 TOTAL LINE K: 245.99

149779 replaced lower ball joint

\*\*\*\*\*

L\*\* replace broken bolts on control arm

65 MISC - DESCRIPTION

903 IUT 0.70 75.99 75.99

PARTS: 0.00 LABOR: 75.99 OTHER: 0.00 TOTAL LINE L: 75.99

149779 removed the broken control arm bolts

\*\*\*\*\*

M\*\* PLEASE REPAIR LEAKY EXHAUST

REPAIR1 Please repair:

903 IUT 1.00 101.00 101.00

PARTS: 0.00 LABOR: 101.00 OTHER: 0.00 TOTAL LINE M: 101.00

149779 welded in a flex pipe

\*\*\*\*\*

INTERNAL PAY SHOP SUPPLIES FOR REPAIR ORDER

2.39

\*\*\*\*\*ALL WHEEL NUTS MUST BE RETORQUED AFTER

100-150 KMS\*\*\*\*\*

COST, SALE, & COMP TOTALS 131644 325706 0

ON BEHALF OF SERVICING DEALER, I HEREBY CERTIFY THAT THE INFORMATION CONTAINED HEREON IS ACCURATE UNLESS OTHERWISE SHOWN. SERVICES DESCRIBED WERE PERFORMED AT NO CHARGE TO OWNER. THERE WAS NO INDICATION FROM THE APPEARANCE OF THE VEHICLE OR OTHERWISE, THAT ANY PART REPAIRED OR REPLACED UNDER THIS CLAIM HAD BEEN CONNECTED IN ANY WAY WITH ANY ACCIDENT, NEGLIGENCE OR MISUSE. RECORDS SUPPORTING THIS CLAIM ARE AVAILABLE FOR (1) YEAR FROM THE DATE OF PAYMENT NOTIFICATION AT THE SERVICING DEALER FOR INSPECTION BY MANUFACTURER'S REPRESENTATIVE.	STATEMENT OF DISCLAIMER	DESCRIPTION	TOTALS	
	The factory warranty constitutes all of the warranties with respect to the sale of this item/items. The Seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.	LABOUR AMOUNT		1944.75
		PARTS AMOUNT		1392.90
		GAS, OIL, LUBE		0.00
		SUBLET AMOUNT		0.00
		MISC. CHARGES		-78.20
		TOTAL CHARGES		3259.45
(SIGNED) DEALER, GENERAL MANAGER OR AUTHORIZED PERSON (DATE)	CUSTOMER SIGNATURE	LESS DEDUCTIBLE	0.00	
		G.S.T. / P.S.T.	0.00	
		<b>PLEASE PAY THIS AMOUNT</b>	<b>3259.45</b>	

HST: 10066 9050 RT0001

INTERNAL COPY