

CUSTOMER #:

109392DA

Bruce Chevrolet Buick GMC Limited

398 Highway 303, RR#2, Digby, NS B0V 1A0

Tel: 902-245-2541 · Fax: 902-245-5157

Toll Free: 1-800-565-3396

www.brucegm.com

customerservice@bruceautogroup.com

INTERNAL

PAGE 1

HOME: CONT:N/A

BUS: CELL: SERVICE ADVISOR: 927 MARYANN POTHIER

COLOUR	YEAR	MAKE/MODEL	VIN	LICENSE	ODOMETER IN/OUT	TAG
GRAY	11	TOYOTA COROLLA	2T1BU4EE0BC677325		94000/94000	T7325

DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
DD			17:00 25NOV15		0.00	CASH	27NOV15

R.O. OPENED	READY	OPTIONS:
12:01 25NOV15	15:32 27NOV15	STK:GD15145B TRN:M

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

A BRUCE SAFETY ONLY - BRUCE SAFETY ONLY USED VEHICLE RECONDITIONING \*\*\*  
\$750 \*\*\*

CAUSE: BRUCE SAFTEY  
CONCERN CODE:

SAFETY BRUCE SAFETY ONLY - BRUCE SAFETY ONLY USED  
VEHICLE RECONDITIONING  
934 IUC 0.70 39.95 39.95

PARTS: 0.00 LABOR: 39.95 OTHER: 0.00 TOTAL LINE A: 39.95

94000 BRUCE SAFTEY BRUCE SAFETY INSPECTION , VEHICLES NEED DRIVER  
SIDE DOOR FIXED DOOR BINDS UP WHEN BEING OPENED DOESN'T SEEM DO ALL THE  
TIME NEEDS DRIVER SIDE WINDOW GLASS BROKE TRYING TO GET THE DOOR OPEN  
\*\*\*\*\*

B 5W30 - LUBE OIL FILTER, INCLUDING 15-POINT INSPECTION  
CAUSE: OIL CHANGE

CONCERN CODE:

530 5W30 - LUBE OIL FILTER, INCLUDING 15-POINT  
INSPECTION  
934 IUC 0.40 24.00 24.00

LOF OIL CHANGE DISCOUNT -14.00 -14.00

1 19299043 \$ELEMENT K 12.50 7.94 7.94

4 88865188 \$OIL 12.99 12.99 51.96

PARTS: 59.90 LABOR: 24.00 OTHER: -14.00 TOTAL LINE B: 69.90

94000 OIL CHANGE CHANGED ENGINE OIL AND FILTER, CHECKED ALL FLUIDS  
\*\*\*\*\*

C INTERNAL GOLD RECON

CONCERN CODE:

80GMZZ102 INTERNAL GOLD RECON  
936 ISUC 5.00 150.00 150.00

PARTS: 0.00 LABOR: 150.00 OTHER: 0.00 TOTAL LINE C: 150.00

94000 internal gold recon complete  
\*\*\*\*\*

\*\*\*\*\*ALL WHEEL NUTS MUST BE RETORQUED AFTER

100-150 KMS\*\*\*\*\*

COST, SALE, & COMP TOTALS 12383 25985 0

DESCRIPTION	TOTALS
ON BEHALF OF SERVICING DEALER, I HEREBY CERTIFY THAT THE INFORMATION CONTAINED HEREON IS ACCURATE UNLESS OTHERWISE SHOWN. SERVICES DESCRIBED WERE PERFORMED AT NO CHARGE TO OWNER. THERE WAS NO INDICATION FROM THE APPEARANCE OF THE VEHICLE OR OTHERWISE, THAT ANY PART REPAIRED OR REPLACED UNDER THIS CLAIM HAD BEEN CONNECTED IN ANY WAY WITH ANY ACCIDENT, NEGLIGENCE OR MISUSE. RECORDS SUPPORTING THIS CLAIM ARE AVAILABLE FOR (1) YEAR FROM THE DATE OF PAYMENT NOTIFICATION AT THE SERVICING DEALER FOR INSPECTION BY MANUFACTURER'S REPRESENTATIVE.	STATEMENT OF DISCLAIMER The factory warranty constitutes all of the warranties with respect to the sale of this item/items. The Seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.
LABOUR AMOUNT	213.95
PARTS AMOUNT	59.90
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	0.00
MISC. CHARGES	-14.00
TOTAL CHARGES	259.85
LESS DEDUCTIBLE	0.00
G.S.T. / P.S.T.	0.00
PLEASE PAY THIS AMOUNT	259.85

HST: 10066 9050 RT0001

INTERNAL COPY