

CUSTOMER #:

372941

Bruce Chevrolet Buick GMC Limited
394 Main Street, Box 970, Middleton, NS B0S 1P0
Tel: 902-825-3494 · Fax: 902-825-2229
Toll Free: 1-800-465-2438
www.brucegm.com

* INTERNAL *

GERALD VEINOTTE
111 KEDDY BRIDGE ROAD
MAHONE BAY NS B0J 2E0
HOME: CONT:902-624-0516
BUS: CELL:

PAGE 1

SERVICE ADVISOR: 813 PAUL MCNEIL

Table with columns: COLOUR, YEAR, MAKE/MODEL, VIN, LICENSE, ODOMETER IN/OUT, TAG. Includes details for GMC SIERRA 1500 and service dates.

Table with columns: LINE, OPCODE, TECH, TYPE, HOURS, LIST, NET, TOTAL.

Main service list table with columns: LINE, OPCODE, TECH, TYPE, HOURS, LIST, NET, TOTAL. Lists various parts and labor items.

Summary and disclaimer table with columns: STATEMENT OF DISCLAIMER, DESCRIPTION, TOTALS. Includes a 'PLEASE PAY THIS AMOUNT' section.

CUSTOMER #:

372941

Bruce Chevrolet Buick GMC Limited
394 Main Street, Box 970, Middleton, NS B0S 1P0
Tel: 902-825-3494 · Fax: 902-825-2229
Toll Free: 1-800-465-2438
www.brucegm.com

* INTERNAL *

GERALD VEINOTTE
111 KEDDY BRIDGE ROAD
MAHONE BAY NS B0J 2E0
HOME: CONT:902-624-0516
BUS: CELL:

PAGE 2

SERVICE ADVISOR: 813 PAUL MCNEIL

Table with columns: COLOUR, YEAR, MAKE/MODEL, VIN, LICENSE, ODOMETER IN/OUT, TAG. Includes details for GMC SIERRA 1500 and service dates.

Table with columns: LINE, OPCODE, TECH, TYPE, HOURS, LIST, NET, TOTAL. Lists various repair items like brake nuts, couplers, and oil filter with associated costs.

completed inspection, found fuel lines leaking and fuel leaking on top of tank, found power steering lines leaking transmission filter leaking, found rear brakes pads worn down and rotors at min spec, parking brake not holding good, vehicle has a clunk in the steering shaft area vehicle also has been critted, vehicle has after market front towing equipment on it

Table with columns: STATEMENT OF DISCLAIMER, DESCRIPTION, TOTALS. Includes a disclaimer on behalf of the servicing dealer and a summary of charges.

CUSTOMER #:

372941

Bruce Chevrolet Buick GMC Limited
394 Main Street, Box 970, Middleton, NS B0S 1P0
Tel: 902-825-3494 · Fax: 902-825-2229
Toll Free: 1-800-465-2438
www.brucegm.com

* INTERNAL *

GERALD VEINOTTE
111 KEDDY BRIDGE ROAD
MAHONE BAY NS B0J 2E0
HOME: CONT:902-624-0516
BUS: CELL:

PAGE 3

SERVICE ADVISOR: 813 PAUL MCNEIL

Table with columns: COLOUR, YEAR, MAKE/MODEL, VIN, LICENSE, ODOMETER IN/OUT, TAG. Includes details for LIGHT_BROW 05 GMC SIERRA 1500 and a summary row with R.O. OPENED, READY, and OPTIONS.

Table with columns: LINE, OPCODE, TECH, TYPE, HOURS, LIST, NET, TOTAL.

system,
changed engine oil and filter,
changed transmission oil filter was leaking and top up fluid
right rear brake line broke in hand when removing , make brake
lines and installed on vehicle and bleed brakes
power steering lines leaking, replaced both pressure lines and
installed new return hose bleed hose
road test vehicle brakes don't feel right bring over hoist and
check over main line run to rear of vehicle blow, run new brake line
and bleed sytem ok now road test vehicle and check over ok now

Table with columns: 65 MISC - DESCRIPTION, 801 IUT 1.80, 1 15098990 BAR, ST WRONG PARTS PASSED OUT, 11 IPP 4.00, 1 20832563 HOSE, 1 15167372 HOSE. Includes labor and other costs.

PARTS: 1050.60 LABOR: 604.76 OTHER: 0.00 TOTAL LINE B: 1655.36
276550 removed old bymper. removed all brackets and plastics from
old bumper and installed on new. reinstalled bumper

*****ALL WHEEL NUTS MUST BE RETORQUED AFTER
100-150 KMS*****

COST, SALE, & COMP TOTALS 272242 432815 0

Table with columns: STATEMENT OF DISCLAIMER, DESCRIPTION, TOTALS. Includes disclaimer text and a summary table with rows for LABOUR AMOUNT, PARTS AMOUNT, GAS, OIL, LUBE, SUBLET AMOUNT, MISC. CHARGES, TOTAL CHARGES, LESS DEDUCTIBLE, G.S.T. / P.S.T., and PLEASE PAY THIS AMOUNT.