

CUSTOMER #:

374812

Bruce Chevrolet Buick GMC Limited
394 Main Street, Box 970, Middleton, NS B0S 1P0
Tel: 902-825-3494 · Fax: 902-825-2229
Toll Free: 1-800-465-2438
www.brucegm.com

INTERNAL

PAGE 1

HOME: CONT:N/A
BUS: CELL:

SERVICE ADVISOR: 813 PAUL MCNEIL

Table with columns: COLOUR, YEAR, MAKE/MODEL, VIN, LICENSE, ODOMETER IN/OUT, TAG. Row 1: GRAY, 13, FORD F-150, 1FTMF1CM7DKE07604, 94681/94681, T699

Table with columns: DEL DATE, PROD. DATE, WARR. EXP., PROMISED, PO NO., RATE, PAYMENT, INV. DATE. Row 1: DD, 17:00 19JUL16, 0.00, CASH, 19JUL16

R.O. OPENED 08:40 19JUL16 READY 15:17 19JUL16 OPTIONS: STK:F16286C DLR:B3366 TRN:AUTO 2)5 YEARS / 100000 KM (B) 3)DIAMOND KOTE PACKAGE (CHEMICAL) 9)GW MOSHER MOTORS LTD

LINE OPCODE TECH TYPE HOURS LIST NET TOTAL

Table with columns: LINE OPCODE, TECH TYPE, HOURS, LIST, NET, TOTAL. Rows include: A BRUCE CERTIFIED USED VEHICLE CHECKLIST, BC BRUCE CERTIFIED USED VEHICLE CHECKLIST, MVI MOTOR VEHICLE INSPECTION, 1U USED VEHICLE : CHECK OLM % AND OIL LEVEL, CHANGE IF 60% OR LESS., 65 license plate assembly replaced, 1 1L3Z13550BA LAMP ASSY

PARTS: 39.71 LABOR: 199.09 OTHER: 0.00 TOTAL LINE A: 238.80
94681 BRUCE CERTIFIED CHECK LIST. ROAD TEST. SERVICE 1 NO OIL CHANGE REQUIRED. REPLACE LEFT LICENCE PLATE LIGHT ASSEMBLY. 2 YEAR MVI STICKER. RADIO NOT WORKING ON ORDER FROM FORD UNDER WARRANTY. AS PER SCOTT

*****ALL WHEEL NUTS MUST BE RETORQUED AFTER 100-150 KMS*****

COST, SALE, & COMP TOTALS 7186 23880 0

Table with columns: STATEMENT OF DISCLAIMER, DESCRIPTION, TOTALS. Rows include: ON BEHALF OF SERVICING DEALER, I HEREBY CERTIFY THAT THE INFORMATION CONTAINED HEREON IS ACCURATE UNLESS OTHERWISE SHOWN. STATEMENT OF DISCLAIMER, LABOUR AMOUNT, PARTS AMOUNT, GAS, OIL, LUBE, SUBLET AMOUNT, MISC. CHARGES, TOTAL CHARGES, LESS DEDUCTIBLE, G.S.T. / P.S.T., PLEASE PAY THIS AMOUNT

INTERNAL COPY