

CUSTOMER #:

382875

Bruce Chevrolet Buick GMC Limited
394 Main Street, Box 970, Middleton, NS B0S 1P0
Tel: 902-825-3494 · Fax: 902-825-2229
Toll Free: 1-800-465-2438
www.brucegm.com

INTERNAL

PAGE 1

HOME: CONT:N/A
BUS: CELL:

SERVICE ADVISOR: 813 PAUL MCNEIL

Table with columns: COLOUR, YEAR, MAKE/MODEL, VIN, LICENSE, ODOMETER IN/OUT, TAG. Values: BLUE, 13, GMC SIERRA 1500, 1GTR1VEA3DZ198531, 98654/98654, T90

Table with columns: DEL DATE, PROD. DATE, WARR. EXP., PROMISED, PO NO., RATE, PAYMENT, INV. DATE. Values: DD, 17:00 21APR17, 0.00, CASH, 25APR17

Table with columns: R.O. OPENED, READY, OPTIONS. Values: 15:57 19APR17, 11:50 25APR17, STK:G17050A TRN:A 3)ULTRA ALL-IN-ONE (ELECTRONIC) 9)GM CANADA

Table with columns: LINE, OPCODE, TECH, TYPE, HOURS, LIST, NET, TOTAL

A MVI OR DETAILED LIST OF WORK REQUIRED FOR MVI

CAUSE: BRUCE CERTIFIED USED VEHICLE CHECKLIST

BC MVI ONLY

Table with columns: LINE, OPCODE, TECH, TYPE, HOURS, LIST, NET, TOTAL. Rows include: 11 IUT 1.20 (100.00), 7 IUT 0.50 (29.15), 45 REPLACE THE CAP LIGHT ON THE REAR (60.00), 1 106860 LAMP (50.00), 2 5555160 CRIMP (1.17)

PARTS: 52.34 LABOR: 189.15 OTHER: 0.00 TOTAL LINE A: 241.49

98654 ROAD TEST VEHICLE ALL OK, BRING IN SHOP, FRONT TIRES SCOPPLED, MOVE TIRES AROUND ROTATION AND PUT SCOPPLED TIRES ON REAR OF VEHICLE, TIRES AT 7/32S GIVE OR TAKE WITH SCOPPLED, CAP LIGHT NOT WORKING NEEDED TO REPAIR CAP LIGHT INSTALLED NEW ON, LIC PLATE LIGHT NOT WORKING COMPLETED WIRING REPAIR ON LIC PLATE LIGHT, REMOVE LOCKING WHEEL NUTS NO KEY, COMPLETED OIL CHANGE ALL OK BRAKES AT 6/MM AND 7/MM

*****ALL WHEEL NUTS MUST BE RETORQUED AFTER 100-150 KMS*****

COST, SALE, & COMP TOTALS 9552 24149 0

Table with columns: STATEMENT OF DISCLAIMER, DESCRIPTION, TOTALS. Includes disclaimer text and summary rows: LABOUR AMOUNT (189.15), PARTS AMOUNT (52.34), TOTAL CHARGES (241.49), G.S.T./P.S.T. (0.00), PLEASE PAY THIS AMOUNT (241.49)

INTERNAL COPY