

CUSTOMER #:

387779

Bruce Chevrolet Buick GMC Limited
394 Main Street, Box 970, Middleton, NS B0S 1P0
Tel: 902-825-3494 · Fax: 902-825-2229
Toll Free: 1-800-465-2438
www.brucegm.com

INTERNAL

PAGE 1

HOME: CONT:N/A
BUS: CELL:

SERVICE ADVISOR: 129 Samantha Hurlburt

Table with vehicle details: COLOUR, YEAR (13), MAKE/MODEL (HONDA CIVIC), VIN (2HGFB2E54DH011638), LICENSE, ODOMETER IN/OUT (120360/120380), TAG (T8), DEL DATE, PROD. DATE, WARR. EXP., PROMISED (17:00 10OCT17), PO NO., RATE (0.00), PAYMENT (CASH), INV. DATE (12OCT17), R.O. OPENED, READY, OPTIONS: STK:L1809B DLR:B3366 TRN:5_SPEED_MANUAL

Table with repair details: LINE, OPCODE, TECH, TYPE, HOURS, LIST, NET, TOTAL. Includes items like BRUCE SAFETY USED VEHICLE RECONDITIONING, 7IUCLS 0.70 (75.00), 1 44018-SNE-A22 BOOT SET (78.10), 1 MS608104 LINK KIT (59.60), RT ROAD TEST USED VEHICLE (30.00), 1U USED VEHICLE : CHECK OLM % AND OIL LEVEL (25.95), 65 install oem muffler (125.88), 52GMZ INSTALL SWAY BAR LINK (60.00), 63 INSTALL AXLE BOOT (224.88)

PARTS: 137.70 LABOR: 541.71 OTHER: 0.00 TOTAL LINE A: 679.41
120380 BRUCE MVI ONLY INSPECTION AND WORK SHEET. ROAD TEST. SERVICE
1 WITH OIL CHANGE RE SET OIL MONITOR. TIGHTEN RIGHT REAR SWAY BAR LINK
.3 HRS. REMOVE AFTER MARKET EXHAUST WELD STOCK EXHAUST BACK IN CAR 1.2
HRS. ORDERED LEFT OUTER C/V BOOT KIT FROM HONDA. ORDERED L/F SWAY BAR
LINK FROM AUTO CHOICE RICES TO REPLACE WINDSHIELD WED. OCT 18 THEN NEW
MVI STICKER. REMOVE LEFT FRONT AXEL REPLACE OUTER C/V BOOT RE PACK
JOINT 1.5 HRS REPLACE LEFT FRONT SWAY BAR LINK. DELIVER TO SPA STILL
NEEDS WINDSHIELD.

*** WHEEL NUTS MUST BE RE-TORQUED WITHIN
150KM OF YOUR SERVICE VISIT ***

COST, SALE, & COMP TOTALS 19125 67941 0

Table with columns: STATEMENT OF DISCLAIMER, DESCRIPTION, TOTALS. Includes rows for LABOUR AMOUNT (541.71), PARTS AMOUNT (137.70), GAS, OIL, LUBE (0.00), SUBLET AMOUNT (0.00), MISC. CHARGES (0.00), TOTAL CHARGES (679.41), LESS DEDUCTIBLE (0.00), G.S.T./P.S.T. (0.00), and PLEASE PAY THIS AMOUNT (679.41)

INTERNAL COPY