

CUSTOMER #:

122565DA

Bruce Chevrolet Buick GMC Limited

398 Highway 303, RR#2, Digby, NS B0V 1A0

Tel: 902-245-2541 · Fax: 902-245-5157

Toll Free: 1-800-565-3396

www.brucegm.com

customerservice@bruceautogroup.com

INTERNAL

PAGE 1

HOME: CONT:N/A

BUS: CELL: SERVICE ADVISOR: 918 RICHARD MILLNER

COLOUR	YEAR	MAKE/MODEL	VIN	LICENSE	ODOMETER IN/OUT	TAG
BLACK	14	RAM TRUCKS 1500	1C6RR7HT4ES276110		59000/59000	T61109

DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
DD			18:00 07NOV17		99.95	CASH	08NOV17

R.O. OPENED	READY	OPTIONS: STK:GD17189A TRN:A
17:06 06NOV17	08:19 08NOV17	

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

A BRUCE SAFETY USED VEHICLE RECONDITIONING, PLEASE PROVIDE WRITTEN LIST OF REPAIRS NEEDED

CONCERN CODE:

BS BRUCE SAFETY USED VEHICLE RECONDITIONING, PLEASE PROVIDE WRITTEN LIST OF REPAIRS NEEDED

915	IUT	0.00			19.69	19.69
921	IUT	0.70			30.31	30.31
		0.70			50.00	50.00
1	CQ515151 HUB				380.00	380.00

RT ROAD TEST USED VEHICLE. CHECK FOR BRAKE PULSATION AND NOTE ANY UNUSUAL NOISES. CHECK A/C AND HEAT.

915	IUT	0.30			30.00	30.00
-----	-----	------	--	--	-------	-------

1U USED RECONDITIONING - LUBE OIL FILTER, INCLUDING 15-POINT INSPECTION

915	IUT	0.40			24.00	24.00
1	19303975 \$FILTER				14.23	6.95
7	19264716X 5W20 BULK				4.00	4.00

PARTS: 414.95 LABOR: 104.00 OTHER: 0.00 TOTAL LINE A: 518.95

59000
OIL CHANGE -921
bruce safety - 915
road test -915

B FOUR WHEEL BRAKE SERVICE (TRUCK) - REMOVE BRAKE DUST AND CORROSION FROM ALL BRAKE COMPONENTS, LUBRICATE ALL MOVING PARTS, CHECK BRAKE FLUID LEVELS AND INSPECT BRAKE SYSTEM

CAUSE: LF MM / RF MM/ LR MM/ RR MM

CONCERN CODE:

2001 FOUR WHEEL BRAKE SERVICE (TRUCK) - REMOVE BRAKE DUST AND CORROSION FROM ALL BRAKE COMPONENTS, LUBRICATE ALL MOVING PARTS, CHECK BRAKE FLUID LEVELS AND INSPECT BRAKE

ON BEHALF OF SERVICING DEALER, I HEREBY CERTIFY THAT THE INFORMATION CONTAINED HEREON IS ACCURATE UNLESS OTHERWISE SHOWN. SERVICES DESCRIBED WERE PERFORMED AT NO CHARGE TO OWNER. THERE WAS NO INDICATION FROM THE APPEARANCE OF THE VEHICLE OR OTHERWISE, THAT ANY PART REPAIRED OR REPLACED UNDER THIS CLAIM HAD BEEN CONNECTED IN ANY WAY WITH ANY ACCIDENT, NEGLIGENCE OR MISUSE. RECORDS SUPPORTING THIS CLAIM ARE AVAILABLE FOR (1) YEAR FROM THE DATE OF PAYMENT NOTIFICATION AT THE SERVICING DEALER FOR INSPECTION BY MANUFACTURER'S REPRESENTATIVE.	STATEMENT OF DISCLAIMER The factory warranty constitutes all of the warranties with respect to the sale of this item/items. The Seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.	DESCRIPTION	TOTALS
		LABOUR AMOUNT	
		PARTS AMOUNT	
		GAS, OIL, LUBE	
		SUBLET AMOUNT	
		MISC. CHARGES	
		TOTAL CHARGES	
		LESS DEDUCTIBLE	
		G.S.T. / P.S.T.	
		PLEASE PAY THIS AMOUNT	

(SIGNED) DEALER, GENERAL MANAGER OR AUTHORIZED PERSON (DATE)

CUSTOMER SIGNATURE

HST: 10066 9050 RT0001

INTERNAL COPY

CUSTOMER #:

122565DA

Bruce Chevrolet Buick GMC Limited

398 Highway 303, RR#2, Digby, NS B0V 1A0

Tel: 902-245-2541 · Fax: 902-245-5157

Toll Free: 1-800-565-3396

www.brucegm.com

customerservice@bruceautogroup.com

INTERNAL

PAGE 2

HOME: CONT:N/A

BUS: CELL: SERVICE ADVISOR: 918 RICHARD MILLNER

COLOUR	YEAR	MAKE/MODEL	VIN	LICENSE	ODOMETER IN/OUT	TAG
BLACK	14	RAM TRUCKS 1500	1C6RR7HT4ES276110		59000/59000	T61109

DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
DD			18:00 07NOV17		99.95	CASH	08NOV17

R.O. OPENED	READY	OPTIONS:	STK:GD17189A TRN:A				
17:06 06NOV17	08:19 08NOV17						

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

SYSTEM							
	915	IUT		1.20		89.95	89.95
PARTS:	0.00	LABOR:		89.95	OTHER:	0.00	TOTAL LINE B: 89.95

59000 4 wheel brake service complete

C** REPLACE LEFT FRONT WHEEL BEARING AS PER LINE A
 CONCERN CODE:

NOTE ADDED NOTE							
	915	IUT		1.30		130.00	130.00
PARTS:	0.00	LABOR:		130.00	OTHER:	0.00	TOTAL LINE C: 130.00

59000 removed and replaced left front hub

*****ALL WHEEL NUTS MUST BE RETORQUED AFTER
 100-150 KMS*****

COST, SALE, & COMP TOTALS 28516 73890 0

ON BEHALF OF SERVICING DEALER, I HEREBY CERTIFY THAT THE INFORMATION CONTAINED HEREON IS ACCURATE UNLESS OTHERWISE SHOWN. SERVICES DESCRIBED WERE PERFORMED AT NO CHARGE TO OWNER. THERE WAS NO INDICATION FROM THE APPEARANCE OF THE VEHICLE OR OTHERWISE, THAT ANY PART REPAIRED OR REPLACED UNDER THIS CLAIM HAD BEEN CONNECTED IN ANY WAY WITH ANY ACCIDENT, NEGLIGENCE OR MISUSE. RECORDS SUPPORTING THIS CLAIM ARE AVAILABLE FOR (1) YEAR FROM THE DATE OF PAYMENT NOTIFICATION AT THE SERVICING DEALER FOR INSPECTION BY MANUFACTURER'S REPRESENTATIVE.	STATEMENT OF DISCLAIMER	DESCRIPTION	TOTALS	
	(SIGNED) DEALER, GENERAL MANAGER OR AUTHORIZED PERSON (DATE)	The factory warranty constitutes all of the warranties with respect to the sale of this item/items. The Seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.	LABOUR AMOUNT	323.95
			PARTS AMOUNT	414.95
			GAS, OIL, LUBE	0.00
			SUBLET AMOUNT	0.00
			MISC. CHARGES	0.00
			TOTAL CHARGES	738.90
			LESS DEDUCTIBLE	0.00
		G.S.T. / P.S.T.	0.00	
	CUSTOMER SIGNATURE	PLEASE PAY THIS AMOUNT	738.90	

HST: 10066 9050 RT0001

INTERNAL COPY