

CUSTOMER #: N/A

17524

INTERNAL

Bruce Hyundai

5482 Prospect Road, New Minas, NS B4N 3K8

Tel: 902-681-3311 · Fax: 902-681-0454

Toll Free: 1-877-681-3232

www.brucehyundai.com

PAGE 1

HOME: CONT:N/A

BUS: CELL: SERVICE ADVISOR: 728 Erin Deveau

COLOUR	YEAR	MAKE/MODEL	VIN	LICENSE	ODOMETER IN/OUT	TAG
	15	HYUNDAI TUCSON	KM8JUCAG7FU083218		78760/78760	TG218

DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
DD			17:00 04DEC17		0.00	CASH	05DEC17

R.O. OPENED	READY	OPTIONS:	STK:YN17517A DLR:8719 TRN:M				
14:51 04DEC17	16:18 05DEC17						

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

A MOTOR VEHICLE INSPECTION - PLEASE PROVIDE LIST
MVI MOTOR VEHICLE INSPECTION
709 IUC 0.50 29.95 29.95
PARTS: 0.00 LABOR: 29.95 OTHER: 0.00 TOTAL LINE A: 29.95
78122 0.50 Completed. MVI

B USED CAR RECONDITIONING WITH PICTURES
URP USED CAR RECONDITIONING WITH PICTURES
733 ISUC 5.30 200.00 200.00
PARTS: 0.00 LABOR: 200.00 OTHER: 0.00 TOTAL LINE B: 200.00

C** MAINTENANCE 1 SERVICE - LUBE, OIL FILTER, 15-POINT INSPECTION
\$47.95
1 MAINTENANCE 1 SERVICE - LUBE, OIL FILTER,
15-POINT INSPECTION \$47.95
709 IUC 0.40 22.95 22.95
1 26300-35504 FILTER ASS 9.23 7.00 7.00
1 21513-23001 GASKET-OIL 0.97 0.63 0.63
5 GTX5W20 GTX5W20 0001500 2.69 2.69 13.45
PARTS: 21.08 LABOR: 22.95 OTHER: 0.00 TOTAL LINE C: 44.03
78122 0.40
#1 service check completed as per customer request.
Front tires have /32 remaining, rear tires have /32 remaining,
added windshield washer, no charge, MVI due

D** FRONT BRAKE SERVICE - REMOVE BRAKE DUST AND CORROSION FROM ALL
BRAKE COMPONENTS, LUBRICATE ALL MOVING PARTS, CHECK BRAKE FLUID
LEVELS AND INSPECT BRAKE SYSTEM. \$69.95
BFS FRONT BRAKE SERVICE - REMOVE BRAKE DUST AND
CORROSION FROM ALL BRAKE COMPONENTS,
LUBRICATE ALL MOVING PARTS, CHECK BRAKE
FLUID LEVELS AND INSPECT BRAKE SYSTEM.
\$69.95
709 IUC 0.80 69.95 69.95

ON BEHALF OF SERVICING DEALER, I HEREBY CERTIFY THAT THE INFORMATION CONTAINED HEREON IS ACCURATE UNLESS OTHERWISE SHOWN. SERVICES DESCRIBED WERE PERFORMED AT NO CHARGE TO OWNER. THERE WAS NO INDICATION FROM THE APPEARANCE OF THE VEHICLE OR OTHERWISE, THAT ANY PART REPAIRED OR REPLACED UNDER THIS CLAIM HAD BEEN CONNECTED IN ANY WAY WITH ANY ACCIDENT, NEGLIGENCE OR MISUSE. RECORDS SUPPORTING THIS CLAIM ARE AVAILABLE FOR (1) YEAR FROM THE DATE OF PAYMENT NOTIFICATION AT THE SERVICING DEALER FOR INSPECTION BY MANUFACTURER'S REPRESENTATIVE.	STATEMENT OF DISCLAIMER	DESCRIPTION	TOTALS	
	(SIGNED) DEALER, GENERAL MANAGER OR AUTHORIZED PERSON (DATE)	The factory warranty constitutes all of the warranties with respect to the sale of this item/items. The Seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.	LABOUR AMOUNT	
			PARTS AMOUNT	
			GAS, OIL, LUBE	
			SUBLET AMOUNT	
			MISC. CHARGES	
			TOTAL CHARGES	
			LESS DEDUCTIBLE	
			G.S.T. / P.S.T.	
			CUSTOMER SIGNATURE	PLEASE PAY THIS AMOUNT

HST: 730 937 893 RT0001

CUSTOMER #: N/A

17524

INTERNAL

Bruce Hyundai

5482 Prospect Road, New Minas, NS B4N 3K8

Tel: 902-681-3311 · Fax: 902-681-0454

Toll Free: 1-877-681-3232

www.brucehyundai.com

PAGE 2

HOME: CONT:N/A
BUS: CELL:

SERVICE ADVISOR: 728 Erin Deveau

COLOUR	YEAR	MAKE/MODEL	VIN	LICENSE	ODOMETER IN/OUT	TAG
	15	HYUNDAI TUCSON	KM8JUCAG7FU083218		78760/78760	TG218

DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
DD			17:00 04DEC17		0.00	CASH	05DEC17

R.O. OPENED	READY	OPTIONS:	STK:YN17517A DLR:8719 TRN:M				
14:51 04DEC17	16:18 05DEC17						

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
PARTS:		0.00	LABOR:	69.95	OTHER:	0.00	TOTAL LINE D: 69.95

78122 0.80 service front brakes 7/mm

 E** REPLACE REAR BRAKE PADS & ROTORS - REPLACE REAR BRAKE PADS AND ROTORS
 BRPR REPLACE REAR BRAKE PADS & ROTORS - REPLACE REAR BRAKE PADS AND ROTORS

709 IUC	1.50			134.95	134.95
2 58411-3A300 DISC-REAR				56.20	56.20
1 58302-2SA10 PAD KIT-RE				72.37	72.37

PARTS:	184.77	LABOR:	134.95	OTHER:	0.00	TOTAL LINE E:	319.72
78122 1.50	install 2 rear rotors and rear pads						

EST: 512.72 04DEC17 16:09 SA: 728

INTERNAL PAY SSUPPLY FOR REPAIR ORDER 50.00

HYUNDAI SIGNATURE SERVICE
 Were you greeted within 60 seconds?
 Was a vehicle "Walk-Around" completed?
 Did we keep you updated on your vehicle?
 Was your vehicle returned cleaner?
 We will follow up with you within 48 hours to make sure you had a great experience with us!

COST, SALE, & COMP TOTALS 30266 66365 0

ON BEHALF OF SERVICING DEALER, I HEREBY CERTIFY THAT THE INFORMATION CONTAINED HEREON IS ACCURATE UNLESS OTHERWISE SHOWN. SERVICES DESCRIBED WERE PERFORMED AT NO CHARGE TO OWNER. THERE WAS NO INDICATION FROM THE APPEARANCE OF THE VEHICLE OR OTHERWISE, THAT ANY PART REPAIRED OR REPLACED UNDER THIS CLAIM HAD BEEN CONNECTED IN ANY WAY WITH ANY ACCIDENT, NEGLIGENCE OR MISUSE. RECORDS SUPPORTING THIS CLAIM ARE AVAILABLE FOR (1) YEAR FROM THE DATE OF PAYMENT NOTIFICATION AT THE SERVICING DEALER FOR INSPECTION BY MANUFACTURER'S REPRESENTATIVE.	STATEMENT OF DISCLAIMER	DESCRIPTION	TOTALS	
	(SIGNED) DEALER, GENERAL MANAGER OR AUTHORIZED PERSON (DATE)	The factory warranty constitutes all of the warranties with respect to the sale of this item/items. The Seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.	LABOUR AMOUNT	457.80
			PARTS AMOUNT	205.85
			GAS, OIL, LUBE	0.00
			SUBLET AMOUNT	0.00
			MISC. CHARGES	50.00
			TOTAL CHARGES	713.65
LESS DEDUCTIBLE			0.00	
		G.S.T. / P.S.T.	0.00	
	CUSTOMER SIGNATURE	PLEASE PAY THIS AMOUNT	713.65	

HST: 730 937 893 RT0001