

CUSTOMER #:

110166D

Bruce Chevrolet Buick GMC Limited

398 Highway 303, RR#2, Digby, NS B0V 1A0

Tel: 902-245-2541 · Fax: 902-245-5157

Toll Free: 1-800-565-3396

www.brucegm.com

customerservice@bruceautogroup.com

INTERNAL

PAGE 1

HOME: CONT:N/A

BUS: CELL: SERVICE ADVISOR: 927 MARYANN POTHIER

COLOUR	YEAR	MAKE/MODEL	VIN	LICENSE	ODOMETER IN/OUT	TAG
BLACK	14	GMC SIERRA 1500	3GTU2VEC6EG133182		99000/99000	T3182

DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
DD			17:00 18JAN16		0.00	CASH	26JAN16

R.O. OPENED READY OPTIONS: STK:G15659A TRN:A

09:49 18JAN16 16:48 26JAN16

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

A BRUCE SAFETY USED VEHICLE RECONDITIONING, PLEASE PROVIDE WRITTEN LIST OF REPAIRS NEEDED ***\$700***

CAUSE: OIL CHANGE

BS BRUCE SAFETY USED VEHICLE RECONDITIONING, PLEASE PROVIDE WRITTEN LIST OF REPAIRS NEEDED

921	IUT	0.00			17.79	17.79
934	IUT	0.70			32.21	32.21
		0.70			50.00	50.00

RT ROAD TEST USED VEHICLE. CHECK FOR BRAKE PULSATION AND NOTE ANY UNUSUAL NOISES. CHECK A/C AND HEAT.

921	IUT	0.30			30.00	30.00
-----	-----	------	--	--	-------	-------

1U USED RECONDITIONING - LUBE OIL FILTER, INCLUDING 15-POINT INSPECTION

921	IUT	0.40			24.00	24.00
1	19330000	\$FILTER		20.79	7.95	7.95
8	88865443	\$OIL		5.62	5.62	44.96

SUBL replaced broken windshield

IUT					410.00	410.00
-----	--	--	--	--	--------	--------

PARTS: 52.91 LABOR: 104.00 OTHER: 410.00 TOTAL LINE A: 566.91

99000 OIL CHANGE CHANGED ENGINE OIL AND FILTER, CHECKED ALL FLUIDS AND LUBED ALL HINGES (934) BRUCE SAFETY , VEHICLE NEEDS FRONT WINDSHIELD REPLACED , CRACK IS IN THE LINE OF VISION

B INTERNAL GOLD RECON

80GMZZ102 INTERNAL GOLD RECON

293	ISUT	2.50			81.71	81.71
936	ISUT	2.50			68.29	68.29
		5.00			150.00	150.00

PARTS: 0.00 LABOR: 150.00 OTHER: 0.00 TOTAL LINE B: 150.00

99000 INTERNAL GOLD RECON COMPLETE

C PICTURES TAKEN AND UPLOADED

ON BEHALF OF SERVICING DEALER, I HEREBY CERTIFY THAT THE INFORMATION CONTAINED HEREON IS ACCURATE UNLESS OTHERWISE SHOWN. SERVICES DESCRIBED WERE PERFORMED AT NO CHARGE TO OWNER. THERE WAS NO INDICATION FROM THE APPEARANCE OF THE VEHICLE OR OTHERWISE, THAT ANY PART REPAIRED OR REPLACED UNDER THIS CLAIM HAD BEEN CONNECTED IN ANY WAY WITH ANY ACCIDENT, NEGLIGENCE OR MISUSE. RECORDS SUPPORTING THIS CLAIM ARE AVAILABLE FOR (1) YEAR FROM THE DATE OF PAYMENT NOTIFICATION AT THE SERVICING DEALER FOR INSPECTION BY MANUFACTURER'S REPRESENTATIVE.	STATEMENT OF DISCLAIMER	DESCRIPTION	TOTALS	
	The factory warranty constitutes all of the warranties with respect to the sale of this item/items. The Seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.	LABOUR AMOUNT		
		PARTS AMOUNT		
		GAS, OIL, LUBE		
		SUBLET AMOUNT		
		MISC. CHARGES		
		TOTAL CHARGES		
		LESS DEDUCTIBLE		
		G.S.T. / P.S.T.		
		PLEASE PAY THIS AMOUNT		
(SIGNED) DEALER, GENERAL MANAGER OR AUTHORIZED PERSON (DATE)	CUSTOMER SIGNATURE			

HST: 10066 9050 RT0001

INTERNAL COPY

CUSTOMER #:

110166D

Bruce Chevrolet Buick GMC Limited

398 Highway 303, RR#2, Digby, NS B0V 1A0

Tel: 902-245-2541 · Fax: 902-245-5157

Toll Free: 1-800-565-3396

www.brucegm.com

customerservice@bruceautogroup.com

INTERNAL

PAGE 2

HOME: CONT:N/A

BUS: CELL: SERVICE ADVISOR: 927 MARYANN POTHIER

COLOUR	YEAR	MAKE/MODEL	VIN	LICENSE	ODOMETER IN/OUT	TAG
BLACK	14	GMC SIERRA 1500	3GTU2VEG6EG133182		99000/99000	T3182

DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
DD			17:00 18JAN16		0.00	CASH	26JAN16

R.O. OPENED READY OPTIONS: STK:G15659A TRN:A

09:49 18JAN16 16:48 26JAN16

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

CAUSE: TAKE PICTURES AND UPLOAD

PICTURES PICTURES TAKEN AND UPLOADED

936 ISUT 0.30

19.95 19.95

PARTS: 0.00 LABOR: 19.95 OTHER: 0.00 TOTAL LINE C: 19.95

99000 PICS TAKEN AND UPLOADED

INTERNAL PAY SHOP SUPPLIES FOR REPAIR ORDER 2.39

*****ALL WHEEL NUTS MUST BE RETORQUED AFTER

100-150 KMS*****

COST, SALE, & COMP TOTALS 52541 73686 0

ON BEHALF OF SERVICING DEALER, I HEREBY CERTIFY THAT THE INFORMATION CONTAINED HEREON IS ACCURATE UNLESS OTHERWISE SHOWN. SERVICES DESCRIBED WERE PERFORMED AT NO CHARGE TO OWNER. THERE WAS NO INDICATION FROM THE APPEARANCE OF THE VEHICLE OR OTHERWISE, THAT ANY PART REPAIRED OR REPLACED UNDER THIS CLAIM HAD BEEN CONNECTED IN ANY WAY WITH ANY ACCIDENT, NEGLIGENCE OR MISUSE. RECORDS SUPPORTING THIS CLAIM ARE AVAILABLE FOR (1) YEAR FROM THE DATE OF PAYMENT NOTIFICATION AT THE SERVICING DEALER FOR INSPECTION BY MANUFACTURER'S REPRESENTATIVE.

STATEMENT OF DISCLAIMER

The factory warranty constitutes all of the warranties with respect to the sale of this item/items. The Seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.

DESCRIPTION	TOTALS
LABOUR AMOUNT	273.95
PARTS AMOUNT	52.91
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	410.00
MISC. CHARGES	2.39
TOTAL CHARGES	739.25
LESS DEDUCTIBLE	0.00
G.S.T. / P.S.T.	0.00
PLEASE PAY THIS AMOUNT	739.25

(SIGNED) DEALER, GENERAL MANAGER OR AUTHORIZED PERSON (DATE)

CUSTOMER SIGNATURE

HST: 10066 9050 RT0001

INTERNAL COPY