

CUSTOMER #:

382313

Bruce Chevrolet Buick GMC Limited
394 Main Street, Box 970, Middleton, NS B0S 1P0
Tel: 902-825-3494 · Fax: 902-825-2229
Toll Free: 1-800-465-2438
www.brucegm.com

INTERNAL

PAGE 1

HOME: CONT:N/A
BUS: CELL:

SERVICE ADVISOR: 813 PAUL MCNEIL

Table with columns: COLOUR, YEAR, MAKE/MODEL, VIN, LICENSE, ODOMETER IN/OUT, TAG. Values: SILVER GRE, 09, GMC ENVOY, 1GKDT33S792120553, 123002/123002, TM53.

Table with columns: DEL DATE, PROD. DATE, WARR. EXP., PROMISED, PO NO., RATE, PAYMENT, INV. DATE. Values: DD, 17:00 30MAR17, 0.00, CASH, 30MAR17.

R.O. OPENED 14:27 30MAR17 READY 16:25 30MAR17 OPTIONS: STK:G17300B TRN:A

Table with columns: LINE, OPCODE, TECH, TYPE, HOURS, LIST, NET, TOTAL. Contains repair details like 'BRUCE SAFETY USED VEHICLE RECONDITIONING' and 'REPLACED BOTH REAR SWAY BAR LINKS'.

PARTS: 154.72 LABOR: 200.00 OTHER: -41.21 TOTAL LINE A: 313.51
123002 1 PERFORMED BRUCE SAFETY. 2 ROAD TEST. (NEEDS REAR SWAY BAR END LINKS FOR MVI. INSIDE OF REAR ROTORS RUSTED, PLAY IN STEERING WHEEL) 3 REPLACED BOTH REAR SWAY BAR END LINKS.

*****ALL WHEEL NUTS MUST BE RETORQUED AFTER 100-150 KMS*****

COST, SALE, & COMP TOTALS 15314 31351 0

Table with columns: STATEMENT OF DISCLAIMER, DESCRIPTION, TOTALS. Includes disclaimer text and a summary table with rows like LABOUR AMOUNT (200.00), PARTS AMOUNT (154.72), TOTAL CHARGES (313.51).

INTERNAL COPY