

CUSTOMER #:

388058

Bruce Chevrolet Buick GMC Limited
394 Main Street, Box 970, Middleton, NS B0S 1P0
Tel: 902-825-3494 · Fax: 902-825-2229
Toll Free: 1-800-465-2438
www.brucegm.com

INTERNAL

PAGE 1

HOME: CONT:N/A
BUS: CELL:

SERVICE ADVISOR: 129 Samantha Hurlburt

Table with columns: COLOUR, YEAR, MAKE/MODEL, VIN, LICENSE, ODOMETER IN/OUT, TAG. Values: SILVER, 13, BUICK ENCLAVE, 5GAKRCKD9DJ179558, 80303/80303, T58

Table with columns: DEL DATE, PROD. DATE, WARR. EXP., PROMISED, PO NO., RATE, PAYMENT, INV. DATE. Values: DD, 17:00 19OCT17, 0.00, CASH, 19OCT17

Table with columns: R.O. OPENED, READY, OPTIONS. Values: 09:42 19OCT17, 10:59 19OCT17, STK:G17623A TRN:A 9)HILLSIDE MOTORS

Table with columns: LINE, OPCODE, TECH, TYPE, HOURS, LIST, NET, TOTAL

Main service items table including: A BRUCE CERTIFIED USED VEHICLE CHECKLIST, BC BRUCE CERTIFIED USED VEHICLE CHECKLIST, MVI MOTOR VEHICLE INSPECTION, 1U USED VEHICLE : CHECK OLM % AND OIL LEVEL, PARTS: 37.76 LABOR: 175.05 OTHER: 0.00 TOTAL LINE A: 212.81

80303 BRUCE CERTIFIED INSPECTION WORK SHEET. ROAD TEST. SERVICE 1
NO OIL CHANGE REQUIRED 65% REMAINING ON OIL. 2 YEAR MVI STICKER.
NOTICED OIL LEAK FRONT OF ENGINE WARRANTY. ALSO ROCK CHIP TO BE FILLED
CENTER LOWER PASSES MVI

\*\*\*\*\*

\*\*\* WHEEL NUTS MUST BE RE-TORQUED WITHIN
150KM OF YOUR SERVICE VISIT \*\*\*

COST, SALE, & COMP TOTALS 7306 21281 0

Table with columns: STATEMENT OF DISCLAIMER, DESCRIPTION, TOTALS. Includes disclaimer text and a summary table with rows: LABOUR AMOUNT (175.05), PARTS AMOUNT (37.76), GAS, OIL, LUBE (0.00), SUBLET AMOUNT (0.00), MISC. CHARGES (0.00), TOTAL CHARGES (212.81), LESS DEDUCTIBLE (0.00), G.S.T. / P.S.T. (0.00), PLEASE PAY THIS AMOUNT (212.81)

INTERNAL COPY