

CUSTOMER #: N/A

16250

INTERNAL

**Bruce Hyundai**

5482 Prospect Road, New Minas, NS B4N 3K8

Tel: 902-681-3311 · Fax: 902-681-0454

**Toll Free: 1-877-681-3232**

www.brucehyundai.com

PAGE 1

HOME: CONT:N/A

BUS: CELL: SERVICE ADVISOR: 707 Kelly Graves

COLOUR	YEAR	MAKE/MODEL	VIN	LICENSE	ODOMETER IN/OUT	TAG
	13	DODGE RAM	1C6RR7LT3DS636280		96486/96486	TG280

DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
DD			17:00 24OCT17		0.00	CASH	26OCT17

R.O. OPENED	READY	OPTIONS: STK:YN17507A TRN:M
12:50 24OCT17	14:07 26OCT17	

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

A BRUCE CERTIFIED USED VEHICLE							
BC BRUCE CERTIFIED USED VEHICLE RECONDITIONING							
	711	IUCO	1.20			119.95	119.95
MVI MOTOR VEHICLE INSPECTION							
	711	IUCO	0.50			29.95	29.95
1 MAINTENANCE 1 SERVICE - LUBE, OIL FILTER, 15-POINT INSPECTION \$47.95							
	711	IUCO	0.40			22.95	22.95
	1	857060			4.11	4.11	4.11
	5	084NA-26018A 5W20 BULK			4.27	2.60	13.00
	1	21513-23001 GASKET-OIL			0.97	0.63	0.63
PARTS:	17.74	LABOR:	172.85	OTHER:	0.00	TOTAL LINE A:	190.59
96486 2.10 bruce check mvi lof done							

\*\*\*\*\*

B USED CAR RECONDITIONING WITH PICTURES

URP USED CAR RECONDITIONING WITH PICTURES							
	733	ISUCO	5.30			200.00	200.00
PARTS:	0.00	LABOR:	200.00	OTHER:	0.00	TOTAL LINE B:	200.00

\*\*\*\*\*

C\*\* REPLACE REAR BRAKE PADS & ROTORS - REPLACE REAR BRAKE PADS AND ROTORS

BRPR REPLACE REAR BRAKE PADS & ROTORS - REPLACE REAR BRAKE PADS AND ROTORS							
	711	IUCO	1.50			134.95	134.95
	1	D967M BRAKE PADS			42.22	42.22	42.22
	2	8780082 ROTORS			84.03	84.03	168.06
PARTS:	210.28	LABOR:	134.95	OTHER:	0.00	TOTAL LINE C:	345.23
96486 1.50 replaced rear rotors and pads							

\*\*\*\*\*

D\*\* REPLACE E-BRAKE SHOES & FREE UP PIVOTS

65 MISC - DESCRIPTION							
	711	IUCO	2.00			180.00	180.00
	1	AXS947 E BRAKE SHOES			58.79	58.79	58.79
PARTS:	58.79	LABOR:	180.00	OTHER:	0.00	TOTAL LINE D:	238.79

ON BEHALF OF SERVICING DEALER, I HEREBY CERTIFY THAT THE INFORMATION CONTAINED HEREON IS ACCURATE UNLESS OTHERWISE SHOWN. SERVICES DESCRIBED WERE PERFORMED AT NO CHARGE TO OWNER. THERE WAS NO INDICATION FROM THE APPEARANCE OF THE VEHICLE OR OTHERWISE, THAT ANY PART REPAIRED OR REPLACED UNDER THIS CLAIM HAD BEEN CONNECTED IN ANY WAY WITH ANY ACCIDENT, NEGLIGENCE OR MISUSE. RECORDS SUPPORTING THIS CLAIM ARE AVAILABLE FOR (1) YEAR FROM THE DATE OF PAYMENT NOTIFICATION AT THE SERVICING DEALER FOR INSPECTION BY MANUFACTURER'S REPRESENTATIVE.	STATEMENT OF DISCLAIMER	DESCRIPTION	TOTALS	
	The factory warranty constitutes all of the warranties with respect to the sale of this item/items. The Seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.	LABOUR AMOUNT		
		PARTS AMOUNT		
		GAS, OIL, LUBE		
		SUBLET AMOUNT		
		MISC. CHARGES		
		TOTAL CHARGES		
		LESS DEDUCTIBLE		
		G.S.T. / P.S.T.		
		(SIGNED) DEALER, GENERAL MANAGER OR AUTHORIZED PERSON (DATE)	CUSTOMER SIGNATURE	<b>PLEASE PAY THIS AMOUNT</b>

HST: 730 937 893 RT0001

CUSTOMER #: N/A

16250

INTERNAL

Bruce Hyundai

5482 Prospect Road, New Minas, NS B4N 3K8

Tel: 902-681-3311 · Fax: 902-681-0454

Toll Free: 1-877-681-3232

www.brucehyundai.com

PAGE 2

HOME: CONT:N/A
BUS: CELL:

SERVICE ADVISOR: 707 Kelly Graves

Table with columns: COLOUR, YEAR, MAKE/MODEL, VIN, LICENSE, ODOMETER IN/OUT, TAG. Values: 13, DODGE RAM, 1C6RR7LT3DS636280, 96486/96486, TG280

Table with columns: DEL DATE, PROD. DATE, WARR. EXP., PROMISED, PO NO., RATE, PAYMENT, INV. DATE. Values: DD, 17:00 24OCT17, 0.00, CASH, 26OCT17

Table with columns: R.O. OPENED, READY, OPTIONS. Values: 12:50 24OCT17, 14:07 26OCT17, STK:YN17507A TRN:M

LINE OPCODE TECH TYPE HOURS LIST NET TOTAL

96486 2.00 replaced rear e-brake shoes
\*\*\*\*\*

E\*\* REPLACE RIGHT FRONT AXLE
65 MISC - DESCRIPTION
711 IUCO 2.00 180.00 180.00
1 139256 CV AXLE 232.75 232.75 232.75
PARTS: 232.75 LABOR: 180.00 OTHER: 0.00 TOTAL LINE E: 412.75

96486 2.00 replaced r/f axle
\*\*\*\*\*

F\*\* REPLACE LEFT FRONT STRUT
65 MISC - DESCRIPTION
711 IUCO 1.60 179.88 179.88
1 72292 FRONT STRUT 160.13 160.13 160.13
PARTS: 160.13 LABOR: 179.88 OTHER: 0.00 TOTAL LINE F: 340.01

96486 1.60 replaced l/f strut
\*\*\*\*\*

G\*\* MAINTENANCE 1 SERVICE - LUBE, OIL FILTER, 15-POINT INSPECTION
\$47.95
1 MAINTENANCE 1 SERVICE - LUBE, OIL FILTER,
15-POINT INSPECTION \$47.95
99 IUCO 0.00 0.00 0.00
\*\*\*\*\*

EST: 594.42 24OCT17 13:48 SA: 707

INTERNAL PAY SSUPPLY FOR REPAIR ORDER 50.00

HYUNDAI SIGNATURE SERVICE
Were you greeted within 60 seconds?
Was a vehicle inspection performed?
Did we keep you updated on your vehicle?
Was your vehicle returned cleaner?
We will follow up with you within 48 hours to
make sure you had a great experience with us!

COST, SALE, & COMP TOTALS 78789 172737 0

Table with columns: STATEMENT OF DISCLAIMER, DESCRIPTION, TOTALS. Includes rows for LABOUR AMOUNT, PARTS AMOUNT, GAS, OIL, LUBE, SUBLET AMOUNT, MISC. CHARGES, TOTAL CHARGES, LESS DEDUCTIBLE, G.S.T./P.S.T., and PLEASE PAY THIS AMOUNT.

HST: 730 937 893 RT0001