

CUSTOMER #:

390431

Bruce Chevrolet Buick GMC Limited
394 Main Street, Box 970, Middleton, NS B0S 1P0
Tel: 902-825-3494 · Fax: 902-825-2229
Toll Free: 1-800-465-2438
www.brucegm.com

INTERNAL

PAGE 1

HOME: CONT:N/A
BUS: CELL:

SERVICE ADVISOR: 530 KYLA WHALEN

Table with columns: COLOUR, YEAR, MAKE/MODEL, VIN, LICENSE, ODOMETER IN/OUT, TAG. Includes details for a red GMC Sierra 2500 with VIN 1GTHK23607F511112, license 246188/246188, and tag T12.

Main service list table with columns: LINE, OPCODE, TECH, TYPE, HOURS, LIST, NET, TOTAL. Lists various repairs such as vehicle reconditioning, greasing, and oil changes.

PARTS: 1622.67 LABOR: 2078.90 OTHER: 0.00 TOTAL LINE A: 3701.57

Bottom section containing a statement of disclaimer, a signature line for the dealer, and a table with columns for Description and Totals, including a 'PLEASE PAY THIS AMOUNT' instruction.

CUSTOMER #:

390431

Bruce Chevrolet Buick GMC Limited
394 Main Street, Box 970, Middleton, NS B0S 1P0
Tel: 902-825-3494 · Fax: 902-825-2229
Toll Free: 1-800-465-2438
www.brucegm.com

INTERNAL

PAGE 2

HOME: CONT:N/A
BUS: CELL:

SERVICE ADVISOR: 530 KYLA WHALEN

Table with columns: COLOUR, YEAR, MAKE/MODEL, VIN, LICENSE, ODOMETER IN/OUT, TAG, DEL DATE, PROD. DATE, WARR. EXP., PROMISED, PO NO., RATE, PAYMENT, INV. DATE, R.O. OPENED, READY, OPTIONS.

Table with columns: LINE, OPCODE, TECH, TYPE, HOURS, LIST, NET, TOTAL. Includes detailed service description for 246188.

INTERNAL PAY SHOP SUPPLIES FOR REPAIR ORDER 75.00
\*\*\* WHEEL NUTS MUST BE RE-TORQUED WITHIN 150KM OF YOUR SERVICE VISIT \*\*\*

COST, SALE, & COMP TOTALS 126771 370157 0

Table with columns: STATEMENT OF DISCLAIMER, DESCRIPTION, TOTALS. Includes disclaimer text and a summary of charges.

INTERNAL COPY