

CUSTOMER #:

380807

Bruce Chevrolet Buick GMC Limited
394 Main Street, Box 970, Middleton, NS B0S 1P0
Tel: 902-825-3494 · Fax: 902-825-2229
Toll Free: 1-800-465-2438
www.brucegm.com

INTERNAL

PAGE 1

HOME: CONT:N/A
BUS: CELL:

SERVICE ADVISOR: 813 PAUL MCNEIL

Table with columns: COLOUR, YEAR, MAKE/MODEL, VIN, LICENSE, ODOMETER IN/OUT, TAG. Values: BLUE, 10, CHEVROLET SILVERADO, 3GCRKSEA5AG126611, 106000/105895, T1736.

Table with columns: DEL DATE, PROD. DATE, WARR. EXP., PROMISED, PO NO., RATE, PAYMENT, INV. DATE. Values: DD, 17:00 31JAN17, 0.00, CASH, 02FEB17.

R.O. OPENED READY OPTIONS: STK:G17039A TRN:A

09:51 31JAN17 15:47 02FEB17
LINE OPCODE TECH TYPE HOURS LIST NET TOTAL
A MVI OR LIST OF REPAIRS REQUIERD FOR MVI
CAUSE: BRUCE CERTIFIED USED VEHICLE CHECKLIST
BC MVI ONLY

Table with columns: OPCODE, TECH, TYPE, HOURS, LIST, NET, TOTAL. Rows include: 7 IUT 1.20 (119.95), 7 IUT 0.50 (29.15), 1201 REPLACE TWO WIPER BLADES... (0.00), 2 19252697 BLADE (18.65), 25 REPLACE BOTH LOWER BALL JOINTS (504.00), 2 19209396 STUD KIT (100.98), 65 REPLACE THE LEFT HEADLIGHT BULB (59.88), 1 H1155BP BULB (23.58).

PARTS: 262.84 LABOR: 712.98 OTHER: 0.00 TOTAL LINE A: 975.82
105895

TO BE SOLD MVI ONLY.
BRUCE CERTIFIED CHECK LIST.
ROAD TEST.
SERVICE 1 WITH OIL CHANGE.
CHECK ENGINE LIGHT ON TEST. HAS EVAP CODES AND O2 CODES. ORDERED
VENT VALVE SHOULD BE HERE FRI. FEB 3 .
REPLACE LEFT LOW BEAM, BULB.
REPLACE BOTH WIPER BLADES.
REPLACE BOTH LOOSE LOWER BALL JOINTS.
2 YEAR MVI STICKER.
DELIVER TO SPA.

*****ALL WHEEL NUTS MUST BE RETORQUED AFTER

100-150 KMS*****

COST, SALE, & COMP TOTALS 31487 97582 0

Table with columns: STATEMENT OF DISCLAIMER, DESCRIPTION, TOTALS. Includes rows for LABOUR AMOUNT (712.98), PARTS AMOUNT (262.84), GAS, OIL, LUBE (0.00), SUBLET AMOUNT (0.00), MISC. CHARGES (0.00), TOTAL CHARGES (975.82), LESS DEDUCTIBLE (0.00), G.S.T. / P.S.T. (0.00), and PLEASE PAY THIS AMOUNT (975.82).

INTERNAL COPY