

CUSTOMER #:

127051

Bruce Ford Sales Ltd.

* INTERNAL * 451 Main Street, Box 970, Middleton NS BOS 1P0
Telephone : (902) 825-5555 - Fax: (902) 825-2211
www.bruceford.ca

PAGE 1

HOME: CONT:N/A
BUS: CELL:

SERVICE ADVISOR: 261 Megan ROYER

Table with columns: COLOUR, YEAR, MAKE/MODEL, VIN, LICENSE, ODOMETER IN/OUT, TAG. Includes details for a Mercedes-Benz Truck and service dates.

Table with columns: LINE, OPCODE, TECH, TYPE, HOURS, LIST, NET, TOTAL.

A MOTOR VEHICLE INSPECTION, 2 YEAR INSPECTION
CAUSE: PROVINCIAL INSPECTION
MVI MOTOR VEHICLE INSPECTION, 2 YEAR INSPECTION
100 IUC 0.50 29.15 29.15
138000 mvi check complete

B SERVICE 1 - LUBE, OIL FILTER, 15-POINT INSPECTION
1 SERVICE 1 - LUBE, OIL FILTER, 15-POINT INSPECTION
100 IUC 0.40 21.95 21.95
1 84062 MERCEDES OIL FILTER 38.60 26.50 26.50
2 DEL*5W40*4LSD OIL - ENGINE 49.08 41.72 83.44
138000 service complete

C** MOUNT AND BALANCE TIRES - SET PRESSURES - FOUR TIRES
1003 MOUNT AND BALANCE TIRES - SET PRESSURES - FOUR TIRES
260 IUC 1.00 69.95 69.95
1003 SHOP CHARGE - WHEEL WEIGHTS 6.00 6.00
4 9777*2448100* 265/45R20 108H XL 466.00 274.05 1096.20
4 TTAX TIRE TAX 4.50 4.50 18.00
138000 Removed tires from vehicle, broke down tires and installed new ones then balanced. torque lug nuts and put air pressure to factory spec.

COST, SALE, & COMP TOTALS 108423 135119 0

Table with columns: Privacy Statement, STATEMENT OF DISCLAIMER, DESCRIPTION, TOTALS. Includes a 'PLEASE PAY THIS AMOUNT' section with a total of 1351.19.