

CUSTOMER #:

387635

Bruce Chevrolet Buick GMC Limited
394 Main Street, Box 970, Middleton, NS B0S 1P0
Tel: 902-825-3494 · Fax: 902-825-2229
Toll Free: 1-800-465-2438
www.brucegm.com

INTERNAL

PAGE 1

HOME: CONT:902-665-4115
BUS: CELL:

SERVICE ADVISOR: 129 Samantha Hurlburt

Table with columns: COLOUR, YEAR, MAKE/MODEL, VIN, LICENSE, ODOMETER IN/OUT, TAG. Values: 15, FORD F-150, 1FTEX1EP5FFC41247, 40915/40915, T47

Table with columns: DEL DATE, PROD. DATE, WARR. EXP., PROMISED, PO NO., RATE, PAYMENT, INV. DATE. Values: DD, 17:00 02OCT17, 0.00, CASH, 02OCT17

Table with columns: R.O. OPENED, READY, OPTIONS. Values: 14:59 02OCT17, 16:48 02OCT17, SOLD-STK:F15520 DLR:B3366 TRN:446_-_AUTOMATIC_6_3)WALKAWAY 9)STEELE FORD LINCOLN

Table with columns: LINE, OPCODE, TECH, TYPE, HOURS, LIST, NET, TOTAL

Table with columns: LINE, OPCODE, TECH, TYPE, HOURS, LIST, NET, TOTAL. Rows include: A BRUCE CERTIFIED USED VEHICLE CHECKLIST, BC BRUCE CERTIFIED USED VEHICLE CHECKLIST, MVI MOTOR VEHICLE INSPECTION, 1U USED VEHICLE : CHECK OLM % AND OIL LEVEL, CHANGE IF 60% OR LESS.

PARTS: 0.00 LABOR: 173.10 OTHER: 0.00 TOTAL LINE A: 173.10

40915 BRUCE CERTIFIED INSPECTION WORK SHEET. ROAD TEST NOTICED BRAKE SHAKE. REAR WORST PRICED OUT NEW TALKED TO BERETT AT FORD WANTS TO LEAVE AS IS FOR NOW. SERVICE 1 NO OIL CHANGE REQUIRED. 2 YEAR MVI STICKER. DELIVER TO SPA.

INTERNAL PAY SHOP SUPPLIES FOR REPAIR ORDER 18.71
*** WHEEL NUTS MUST BE RE-TORQUED WITHIN 150KM OF YOUR SERVICE VISIT ***

COST, SALE, & COMP TOTALS 5040 17310 0

Table with columns: STATEMENT OF DISCLAIMER, DESCRIPTION, TOTALS. Rows include: LABOUR AMOUNT (173.10), PARTS AMOUNT (0.00), GAS, OIL, LUBE (0.00), SUBLET AMOUNT (0.00), MISC. CHARGES (18.71), TOTAL CHARGES (191.81), LESS DEDUCTIBLE (0.00), G.S.T. / P.S.T. (0.00), PLEASE PAY THIS AMOUNT (191.81)

INTERNAL COPY