

CUSTOMER #:

123739D

Bruce Chevrolet Buick GMC Limited

398 Highway 303, RR#2, Digby, NS B0V 1A0

Tel: 902-245-2541 · Fax: 902-245-5157

Toll Free: 1-800-565-3396

www.brucegm.com

customerservice@bruceautogroup.com

INTERNAL

PAGE 1

HOME: CONT:N/A

BUS: CELL: SERVICE ADVISOR: 940 NICOLE STARK

COLOUR	YEAR	MAKE/MODEL	VIN	LICENSE	ODOMETER IN/OUT	TAG
STONE BLUE	15	GMC SIERRA 3500	1GT421C80FF632067		67556/67556	T2067

DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
DD			17:00 11JAN18		99.95	CASH	16JAN18

R.O. OPENED	READY	OPTIONS:	STK:GD18136A TRN:A				
16:59 11JAN18	08:41 16JAN18						

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

A BRUCE SAFETY USED VEHICLE RECONDITIONING, PLEASE PROVIDE WRITTEN LIST OF REPAIRS NEEDED

BS BRUCE SAFETY USED VEHICLE RECONDITIONING, PLEASE PROVIDE WRITTEN LIST OF REPAIRS NEEDED

938 ISUT 0.70 50.00 50.00

RT ROAD TEST USED VEHICLE. CHECK FOR BRAKE PULSATION AND NOTE ANY UNUSUAL NOISES. CHECK A/C AND HEAT.

938 ISUT 0.30 30.00 30.00

1U USED RECONDITIONING - LUBE OIL FILTER, INCLUDING 15-POINT INSPECTION

938 ISUT 0.40 24.00 24.00

1 12677108 \$FILTER 20.71 11.00 11.00

10 88861751X OIL 15W40 5.00 4.00 40.00

PARTS: 51.00 LABOR: 104.00 OTHER: 0.00 TOTAL LINE A: 155.00

67556 BRUCE SAFETY , HD MVI , DIESEL OIL CHANGE , ROAD TEST

B FOUR WHEEL BRAKE SERVICE (TRUCK) - REMOVE BRAKE DUST AND CORROSION FROM ALL BRAKE COMPONENTS, LUBRICATE ALL MOVING PARTS, CHECK BRAKE FLUID LEVELS AND INSPECT BRAKE SYSTEM

CAUSE: LF MM / RF MM/ LR MM/ RR MM

2001 FOUR WHEEL BRAKE SERVICE (TRUCK) - REMOVE BRAKE DUST AND CORROSION FROM ALL BRAKE COMPONENTS, LUBRICATE ALL MOVING PARTS,

CHECK BRAKE FLUID LEVELS AND INSPECT BRAKE SYSTEM

938 IUT 1.20 43.25 43.25

943 IUT 0.00 46.70 46.70

1.20 89.95 89.95

PARTS: 0.00 LABOR: 89.95 OTHER: 0.00 TOTAL LINE B: 89.95

67556 PERFORMED BRAKE SERVICE ON REAR BRAKES-943 938

C INTERNAL GOLD RECON

ON BEHALF OF SERVICING DEALER, I HEREBY CERTIFY THAT THE INFORMATION CONTAINED HEREON IS ACCURATE UNLESS OTHERWISE SHOWN. SERVICES DESCRIBED WERE PERFORMED AT NO CHARGE TO OWNER. THERE WAS NO INDICATION FROM THE APPEARANCE OF THE VEHICLE OR OTHERWISE, THAT ANY PART REPAIRED OR REPLACED UNDER THIS CLAIM HAD BEEN CONNECTED IN ANY WAY WITH ANY ACCIDENT, NEGLIGENCE OR MISUSE. RECORDS SUPPORTING THIS CLAIM ARE AVAILABLE FOR (1) YEAR FROM THE DATE OF PAYMENT NOTIFICATION AT THE SERVICING DEALER FOR INSPECTION BY MANUFACTURER'S REPRESENTATIVE.	STATEMENT OF DISCLAIMER	DESCRIPTION	TOTALS	
	(SIGNED) DEALER, GENERAL MANAGER OR AUTHORIZED PERSON (DATE)	The factory warranty constitutes all of the warranties with respect to the sale of this item/items. The Seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.	LABOUR AMOUNT	
			PARTS AMOUNT	
			GAS, OIL, LUBE	
			SUBLET AMOUNT	
			MISC. CHARGES	
			TOTAL CHARGES	
			LESS DEDUCTIBLE	
			G.S.T. / P.S.T.	
			CUSTOMER SIGNATURE	PLEASE PAY THIS AMOUNT

HST: 10066 9050 RT0001

INTERNAL COPY

CUSTOMER #:

123739D

Bruce Chevrolet Buick GMC Limited

398 Highway 303, RR#2, Digby, NS B0V 1A0

Tel: 902-245-2541 · Fax: 902-245-5157

Toll Free: 1-800-565-3396

www.brucegm.com

customerservice@bruceautogroup.com

INTERNAL

PAGE 2

HOME: CONT:N/A

BUS: CELL: SERVICE ADVISOR: 940 NICOLE STARK

COLOUR	YEAR	MAKE/MODEL	VIN	LICENSE	ODOMETER IN/OUT	TAG
STONE BLUE	15	GMC SIERRA 3500	1GT421C80FF632067		67556/67556	T2067

DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
DD			17:00 11JAN18		99.95	CASH	16JAN18

R.O. OPENED	READY	OPTIONS:	STK:GD18136A TRN:A				
16:59 11JAN18	08:41 16JAN18						

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

80GMZZ102	INTERNAL	GOLD	RECON				
	936	ISUT	5.00			150.00	150.00

PARTS:	0.00	LABOR:	150.00	OTHER:	0.00	TOTAL LINE C:	150.00
--------	------	--------	--------	--------	------	---------------	--------

67556 internal gold complete

D PICTURES TAKEN AND UPLOADED
CAUSE: TAKE PICTURES AND UPLOAD

PICTURES PICTURES TAKEN AND UPLOADED

	936	ISUT	0.30			19.95	19.95
--	-----	------	------	--	--	-------	-------

PARTS:	0.00	LABOR:	19.95	OTHER:	0.00	TOTAL LINE D:	19.95
--------	------	--------	-------	--------	------	---------------	-------

67556 pics taken and uploaded

INTERNAL PAY SHOP SUPPLIES FOR REPAIR ORDER 14.87

*****ALL WHEEL NUTS MUST BE RETORQUED AFTER

100-150 KMS*****

COST, SALE, & COMP TOTALS 19442 41490 0

ON BEHALF OF SERVICING DEALER, I HEREBY CERTIFY THAT THE INFORMATION CONTAINED HEREON IS ACCURATE UNLESS OTHERWISE SHOWN. SERVICES DESCRIBED WERE PERFORMED AT NO CHARGE TO OWNER. THERE WAS NO INDICATION FROM THE APPEARANCE OF THE VEHICLE OR OTHERWISE, THAT ANY PART REPAIRED OR REPLACED UNDER THIS CLAIM HAD BEEN CONNECTED IN ANY WAY WITH ANY ACCIDENT, NEGLIGENCE OR MISUSE. RECORDS SUPPORTING THIS CLAIM ARE AVAILABLE FOR (1) YEAR FROM THE DATE OF PAYMENT NOTIFICATION AT THE SERVICING DEALER FOR INSPECTION BY MANUFACTURER'S REPRESENTATIVE.	STATEMENT OF DISCLAIMER	DESCRIPTION	TOTALS	
	(SIGNED) DEALER, GENERAL MANAGER OR AUTHORIZED PERSON (DATE)	The factory warranty constitutes all of the warranties with respect to the sale of this item/items. The Seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.	LABOUR AMOUNT	363.90
			PARTS AMOUNT	51.00
			GAS, OIL, LUBE	0.00
			SUBLET AMOUNT	0.00
			MISC. CHARGES	14.87
			TOTAL CHARGES	429.77
			LESS DEDUCTIBLE	0.00
			G.S.T. / P.S.T.	0.00
			CUSTOMER SIGNATURE	PLEASE PAY THIS AMOUNT

HST: 10066 9050 RT0001

INTERNAL COPY