

CUSTOMER #:

61548

BRUCE HONDA

166 Starrs Road, Yarmouth, NS B5A 4A8

Tel: 902-742-2575 · Fax: 902-742-9150

www.brucehonda.com

INTERNAL

PAGE 1

HOME: CONT:N/A

BUS: CELL: SERVICE ADVISOR: 156 Jordan Jacquard

COLOUR	YEAR	MAKE/MODEL	VIN	LICENSE	ODOMETER IN/OUT	TAG
RED	10	GMC SIERRA 1500	1GTSKUEA7AZ124565		223185/223185	T565

DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
IS DD			19:00 08JAN18			CASH	10JAN18

R.O. OPENED	READY	OPTIONS:	STK:H09876B	DLR:8719	TRN:M
15:48 05JAN18	09:07 10JAN18				

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

A BRUCE MVI ONLY - BRUCE MVI ONLY USED VEHICLE RECONDITIONING. TECHNICIAN TO COMPLETE MVI ONLY INSPECTION CHECKLIST.

BS BRUCE MVI ONLY - BRUCE MVI ONLY USED VEHICLE RECONDITIONING. TECHNICIAN TO COMPLETE MVI ONLY INSPECTION CHECKLIST.

105 IUC 0.70					69.99	69.99
1 H11BP H11 BULB				19.17	19.17	19.17

MVI MOTOR VEHICLE INSPECTION

105 IUC 0.50					29.15	29.15
--------------	--	--	--	--	-------	-------

RT ROAD TEST USED VEHICLE. CHECK FOR BRAKE PULSATION AND NOTE ANY UNUSUAL NOISES. CHECK A/C AND HEAT.

105 IUC 0.30					30.00	30.00
--------------	--	--	--	--	-------	-------

PARTS: 19.17 LABOR: 129.14 OTHER: 0.00 TOTAL LINE A: 148.31

223185 perform mvi

B USED VEHICLE FULL DETAIL - 4.0 HRS
D13 USED VEHICLE FULL DETAIL - 4.0 HRS

251 IUC 4.00					159.88	159.88
--------------	--	--	--	--	--------	--------

PARTS: 0.00 LABOR: 159.88 OTHER: 0.00 TOTAL LINE B: 159.88

C** INSTALL BOTH LWR BALL JOINTS FOR MVI
CAUSE: FRONT AXLE REPAIR

FAXLE install both lwr ball joints

105 IUC 2.10					210.00	210.00
116 IUC 2.10					210.00	210.00

4.20					420.00	420.00
2 72-K6541 BALL JOINT				35.12	35.12	70.24

PARTS: 70.24 LABOR: 420.00 OTHER: 0.00 TOTAL LINE C: 490.24

D** REPLACE RH FRONT UPPER CONTROL ARM
CAUSE: FRONT AXLE REPAIR

FAXLE replace rh upper control arm

105 IUC 0.50					50.00	50.00
--------------	--	--	--	--	-------	-------

ON BEHALF OF SERVICING DEALER, I HEREBY CERTIFY THAT THE INFORMATION CONTAINED HEREON IS ACCURATE UNLESS OTHERWISE SHOWN. SERVICES DESCRIBED WERE PERFORMED AT NO CHARGE TO OWNER. THERE WAS NO INDICATION FROM THE APPEARANCE OF THE VEHICLE OR OTHERWISE, THAT ANY PART REPAIRED OR REPLACED UNDER THIS CLAIM HAD BEEN CONNECTED IN ANY WAY WITH ANY ACCIDENT, NEGLIGENCE OR MISUSE. RECORDS SUPPORTING THIS CLAIM ARE AVAILABLE FOR (1) YEAR FROM THE DATE OF PAYMENT NOTIFICATION AT THE SERVICING DEALER FOR INSPECTION BY MANUFACTURER'S REPRESENTATIVE.	STATEMENT OF DISCLAIMER	DESCRIPTION	TOTALS	
	(SIGNED) DEALER, GENERAL MANAGER OR AUTHORIZED PERSON (DATE)	The factory warranty constitutes all of the warranties with respect to the sale of this item/items. The Seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.	LABOUR AMOUNT	
			PARTS AMOUNT	
			GAS, OIL, LUBE	
			SUBLET AMOUNT	
			MISC. CHARGES	
			TOTAL CHARGES	
			LESS DEDUCTIBLE	
			G.S.T. / P.S.T.	
			CUSTOMER SIGNATURE	PLEASE PAY THIS AMOUNT

HST: 801244898

CUSTOMER #:

61548

BRUCE HONDA

166 Starrs Road, Yarmouth, NS B5A 4A8

Tel: 902-742-2575 · Fax: 902-742-9150

www.brucehonda.com

INTERNAL

PAGE 2

HOME: CONT:N/A

BUS: CELL: SERVICE ADVISOR: 156 Jordan Jacquard

COLOUR	YEAR	MAKE/MODEL	VIN	LICENSE	ODOMETER IN/OUT	TAG
RED	10	GMC SIERRA 1500	1GTSKUEA7AZ124565		223185/223185	T565

DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
IS DD			19:00 08JAN18			CASH	10JAN18

R.O. OPENED	READY	OPTIONS:	STK:H09876B	DLR:8719	TRN:M
15:48 05JAN18	09:07 10JAN18				

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL	
		116	IUC	0.50		50.00	50.00	
				1.00		100.00	100.00	
	1	72-CK80669	CONTROL ARM		148.92	148.92	148.92	
PARTS:		148.92	LABOR:	100.00	OTHER:	0.00	TOTAL LINE D:	248.92
223185 replace left frt upper contorl arm								

E** REPLACE BOTH OUTER AXLE BOOTS

CAUSE: FRONT AXLE REPAIR

FAXLE replace both outer axle boots

		105	IUC	1.48		147.58	147.58	
		116	IUC	1.52		152.42	152.42	
				3.00		300.00	300.00	
	2	DX554	BOOT KIT		50.96	50.96	101.92	
PARTS:		101.92	LABOR:	300.00	OTHER:	0.00	TOTAL LINE E:	401.92

F** REPLACE RH FRONT AXLE SEAL

CAUSE: FRONT AXLE REPAIR

FAXLE replace rh axle seal

		105	IUC	3.00		300.00	300.00	
	1	15270970	GASKET		23.02	23.02	23.02	
	1	22761722	SEAL		34.19	34.19	34.19	
PARTS:		57.21	LABOR:	300.00	OTHER:	0.00	TOTAL LINE F:	357.21

G** WHEEL ALIGNMENT - FOUR WHEEL - SET TOE, CAMBER, CASTER - ROAD TEST

(INCLUDES 0.5H TO FREE UP COMPONENTS)

3001 WHEEL ALIGNMENT - FOUR WHEEL - SET TOE, CAMBER, CASTER - ROAD TEST (INCLUDES 0.5H TO FREE UP COMPONENTS)

		105	IUC	1.00		99.88	99.88	
PARTS:		0.00	LABOR:	99.88	OTHER:	0.00	TOTAL LINE G:	99.88

H** INSTALL INSULATOR

65 MISC - DESCRIPTION

		116	IUC	0.10		8.95	8.95
--	--	-----	-----	------	--	------	------

ON BEHALF OF SERVICING DEALER, I HEREBY CERTIFY THAT THE INFORMATION CONTAINED HEREON IS ACCURATE UNLESS OTHERWISE SHOWN. SERVICES DESCRIBED WERE PERFORMED AT NO CHARGE TO OWNER. THERE WAS NO INDICATION FROM THE APPEARANCE OF THE VEHICLE OR OTHERWISE, THAT ANY PART REPAIRED OR REPLACED UNDER THIS CLAIM HAD BEEN CONNECTED IN ANY WAY WITH ANY ACCIDENT, NEGLIGENCE OR MISUSE. RECORDS SUPPORTING THIS CLAIM ARE AVAILABLE FOR (1) YEAR FROM THE DATE OF PAYMENT NOTIFICATION AT THE SERVICING DEALER FOR INSPECTION BY MANUFACTURER'S REPRESENTATIVE.	STATEMENT OF DISCLAIMER	DESCRIPTION	TOTALS	
	(SIGNED) DEALER, GENERAL MANAGER OR AUTHORIZED PERSON (DATE)	The factory warranty constitutes all of the warranties with respect to the sale of this item/items. The Seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.	LABOUR AMOUNT	
			PARTS AMOUNT	
			GAS, OIL, LUBE	
			SUBLET AMOUNT	
			MISC. CHARGES	
			TOTAL CHARGES	
			LESS DEDUCTIBLE	
			G.S.T. / P.S.T.	
			CUSTOMER SIGNATURE	PLEASE PAY THIS AMOUNT

HST: 801244898

INTERNAL COPY

CUSTOMER #:

61548

BRUCE HONDA

166 Starrs Road, Yarmouth, NS B5A 4A8

Tel: 902-742-2575 · Fax: 902-742-9150

www.brucehonda.com

INTERNAL

PAGE 3

HOME: CONT:N/A

BUS: CELL: SERVICE ADVISOR: 156 Jordan Jacquard

COLOUR	YEAR	MAKE/MODEL	VIN	LICENSE	ODOMETER IN/OUT	TAG
RED	10	GMC SIERRA 1500	1GTSKUEA7AZ124565		223185/223185	T565

DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
	IS DD		19:00 08JAN18			CASH	10JAN18

R.O. OPENED	READY	OPTIONS:	STK:H09876B DLR:8719 TRN:M				
15:48 05JAN18	09:07 10JAN18						

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
2	35230	INSULATOR			19.08	19.08	38.16
PARTS:	38.16	LABOR:	8.95	OTHER:	0.00	TOTAL LINE H:	47.11
223185 replace exhaust hangers							

I MAINTENANCE A SERVICE - NON HONDA, LUBE, OIL FILTER**
 A MAINTENANCE A SERVICE - NON HONDA, LUBE, OIL
 FILTER

105	IUC	0.40				23.20	23.20
1	19303975	GM OIL FILTER			14.39	14.39	14.39
7	S530946	SYN 5W30 DEXO OIL			8.99	8.99	62.93
PARTS:	77.32	LABOR:	23.20	OTHER:	0.00	TOTAL LINE I:	100.52

J CHANGE FRONT DIFF FLUID**
 65 MISC - DESCRIPTION

105	IUC	0.50				44.50	44.50
2	20047	75/90 SYN TRANS DIFF			33.66	33.66	67.32
PARTS:	67.32	LABOR:	44.50	OTHER:	0.00	TOTAL LINE J:	111.82

K PROVINCIAL INSPECTION DUE JANUARY 2020.**
 JAN20 PROVINCIAL INSPECTION DUE JANUARY 2020.

99	ICNC	0.00				0.00	0.00
----	------	------	--	--	--	------	------

 INTERNAL PAY SHOP CHARGE FOR REPAIR ORDER 49.50
 *****ALL WHEEL NUTS MUST BE
 RETORQUED AFTER 100-150 KMS*****

COST, SALE, & COMP TOTALS 60927 216581 0

ON BEHALF OF SERVICING DEALER, I HEREBY CERTIFY THAT THE INFORMATION CONTAINED HEREON IS ACCURATE UNLESS OTHERWISE SHOWN. SERVICES DESCRIBED WERE PERFORMED AT NO CHARGE TO OWNER. THERE WAS NO INDICATION FROM THE APPEARANCE OF THE VEHICLE OR OTHERWISE, THAT ANY PART REPAIRED OR REPLACED UNDER THIS CLAIM HAD BEEN CONNECTED IN ANY WAY WITH ANY ACCIDENT, NEGLIGENCE OR MISUSE. RECORDS SUPPORTING THIS CLAIM ARE AVAILABLE FOR (1) YEAR FROM THE DATE OF PAYMENT NOTIFICATION AT THE SERVICING DEALER FOR INSPECTION BY MANUFACTURER'S REPRESENTATIVE.	STATEMENT OF DISCLAIMER The factory warranty constitutes all of the warranties with respect to the sale of this item/items. The Seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.	DESCRIPTION	TOTALS
		LABOUR AMOUNT	1585.55
		PARTS AMOUNT	580.26
		GAS, OIL, LUBE	0.00
		SUBLET AMOUNT	0.00
		MISC. CHARGES	49.50
		TOTAL CHARGES	2215.31
	LESS DEDUCTIBLE	0.00	
	G.S.T. / P.S.T.	0.00	
(SIGNED) DEALER, GENERAL MANAGER OR AUTHORIZED PERSON (DATE)	CUSTOMER SIGNATURE	PLEASE PAY THIS AMOUNT	2215.31

HST: 801244898

INTERNAL COPY