

CUSTOMER #:

123927D

Bruce Chevrolet Buick GMC Limited

398 Highway 303, RR#2, Digby, NS B0V 1A0

Tel: 902-245-2541 · Fax: 902-245-5157

Toll Free: 1-800-565-3396

www.brucegm.com

customerservice@bruceautogroup.com

INTERNAL

PAGE 1

HOME: CONT:N/A

BUS: CELL: SERVICE ADVISOR: 940 NICOLE STARK

COLOUR	YEAR	MAKE/MODEL	VIN	LICENSE	ODOMETER IN/OUT	TAG
WHITE	16	CHEVROLET SILVERADO	3GCUKREC9GG255741		41087/41087	T5741

DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
DD			17:00 24JAN18		99.95	CASH	25JAN18

R.O. OPENED	READY	OPTIONS:	STK:GD17343A TRN:M				
13:21 24JAN18	16:17 25JAN18						

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

A BRUCE CERTIFIED USED VEHICLE CHECKLIST							
BC BRUCE CERTIFIED USED VEHICLE CHECKLIST							
	938	IUT	1.20			119.95	119.95
	1	19330000	\$FILTER		14.24	12.95	12.95
	8	88865715	\$OIL		5.00	5.00	40.00
MVI MOTOR VEHICLE INSPECTION							
	938	IUT	0.50			29.15	29.15
1U USED RECONDITIONING - LUBE OIL FILTER, INCLUDING 15-POINT INSPECTION							
	938	IUT	0.40			24.00	24.00
PARTS:	52.95	LABOR:	173.10	OTHER:	0.00	TOTAL LINE A:	226.05

41087 BRUCE CERTIFIED , ROAD TEST , MVI , OIL CHANGE TECH 938

B FOUR WHEEL BRAKE SERVICE (TRUCK) - REMOVE BRAKE DUST AND CORROSION FROM ALL BRAKE COMPONENTS, LUBRICATE ALL MOVING PARTS, CHECK BRAKE FLUID LEVELS AND INSPECT BRAKE SYSTEM							
CAUSE: LF MM / RF MM/ LR MM/ RR MM							
2001 FOUR WHEEL BRAKE SERVICE (TRUCK) - REMOVE BRAKE DUST AND CORROSION FROM ALL BRAKE COMPONENTS, LUBRICATE ALL MOVING PARTS, CHECK BRAKE FLUID LEVELS AND INSPECT BRAKE SYSTEM							
	938	IUT	1.20			89.95	89.95

PARTS:	0.00	LABOR:	89.95	OTHER:	0.00	TOTAL LINE B:	89.95
--------	------	--------	-------	--------	------	---------------	-------

41087 FOUR WHEEL BRAKE SERVICE TECH 938

C INTERNAL GOLD RECON							
80GMZZ102 INTERNAL GOLD RECON							
	936	ISUT	5.00			150.00	150.00

PARTS:	0.00	LABOR:	150.00	OTHER:	0.00	TOTAL LINE C:	150.00
--------	------	--------	--------	--------	------	---------------	--------

41087 internal gold complete

D PICTURES TAKEN AND UPLOADED
CAUSE: TAKE PICTURES AND UPLOAD

ON BEHALF OF SERVICING DEALER, I HEREBY CERTIFY THAT THE INFORMATION CONTAINED HEREON IS ACCURATE UNLESS OTHERWISE SHOWN. SERVICES DESCRIBED WERE PERFORMED AT NO CHARGE TO OWNER. THERE WAS NO INDICATION FROM THE APPEARANCE OF THE VEHICLE OR OTHERWISE, THAT ANY PART REPAIRED OR REPLACED UNDER THIS CLAIM HAD BEEN CONNECTED IN ANY WAY WITH ANY ACCIDENT, NEGLIGENCE OR MISUSE. RECORDS SUPPORTING THIS CLAIM ARE AVAILABLE FOR (1) YEAR FROM THE DATE OF PAYMENT NOTIFICATION AT THE SERVICING DEALER FOR INSPECTION BY MANUFACTURER'S REPRESENTATIVE.	STATEMENT OF DISCLAIMER	DESCRIPTION	TOTALS	
	(SIGNED) DEALER, GENERAL MANAGER OR AUTHORIZED PERSON (DATE)	The factory warranty constitutes all of the warranties with respect to the sale of this item/items. The Seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.	LABOUR AMOUNT	
			PARTS AMOUNT	
			GAS, OIL, LUBE	
			SUBLET AMOUNT	
			MISC. CHARGES	
			TOTAL CHARGES	
			LESS DEDUCTIBLE	
			G.S.T. / P.S.T.	
			CUSTOMER SIGNATURE	PLEASE PAY THIS AMOUNT

HST: 10066 9050 RT0001

INTERNAL COPY

CUSTOMER #:

123927D

Bruce Chevrolet Buick GMC Limited

398 Highway 303, RR#2, Digby, NS B0V 1A0

Tel: 902-245-2541 · Fax: 902-245-5157

Toll Free: 1-800-565-3396

www.brucegm.com

customerservice@bruceautogroup.com

INTERNAL

PAGE 2

HOME: CONT:N/A

BUS: CELL: SERVICE ADVISOR: 940 NICOLE STARK

COLOUR	YEAR	MAKE/MODEL	VIN	LICENSE	ODOMETER IN/OUT	TAG
WHITE	16	CHEVROLET SILVERADO	3GCUKREC9GG255741		41087/41087	T5741

DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
DD			17:00 24JAN18		99.95	CASH	25JAN18

R.O. OPENED	READY	OPTIONS:	STK:GD17343A TRN:M				
13:21 24JAN18	16:17 25JAN18						

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

PICTURES PICTURES TAKEN AND UPLOADED							
				936 ISUT	0.30	19.95	19.95

PARTS:	0.00	LABOR:	19.95	OTHER:	0.00	TOTAL LINE D:	19.95
--------	------	--------	-------	--------	------	---------------	-------

41087 pics taken and uploaded

INTERNAL PAY SHOP SUPPLIES FOR REPAIR ORDER 2.39

*****ALL WHEEL NUTS MUST BE RETORQUED AFTER

100-150 KMS*****

COST, SALE, & COMP TOTALS 19865 48595 0

<p>ON BEHALF OF SERVICING DEALER, I HEREBY CERTIFY THAT THE INFORMATION CONTAINED HEREON IS ACCURATE UNLESS OTHERWISE SHOWN. SERVICES DESCRIBED WERE PERFORMED AT NO CHARGE TO OWNER. THERE WAS NO INDICATION FROM THE APPEARANCE OF THE VEHICLE OR OTHERWISE, THAT ANY PART REPAIRED OR REPLACED UNDER THIS CLAIM HAD BEEN CONNECTED IN ANY WAY WITH ANY ACCIDENT, NEGLIGENCE OR MISUSE. RECORDS SUPPORTING THIS CLAIM ARE AVAILABLE FOR (1) YEAR FROM THE DATE OF PAYMENT NOTIFICATION AT THE SERVICING DEALER FOR INSPECTION BY MANUFACTURER'S REPRESENTATIVE.</p>	STATEMENT OF DISCLAIMER	DESCRIPTION	TOTALS			
	<p>The factory warranty constitutes all of the warranties with respect to the sale of this item/items. The Seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.</p>	<p>LABOUR AMOUNT 433.00 PARTS AMOUNT 52.95 GAS, OIL, LUBE 0.00 SUBLET AMOUNT 0.00 MISC. CHARGES 2.39 TOTAL CHARGES 488.34 LESS DEDUCTIBLE 0.00 G.S.T. / P.S.T. 0.00</p>	PLEASE PAY THIS AMOUNT	488.34		
			(SIGNED) DEALER, GENERAL MANAGER OR AUTHORIZED PERSON (DATE)	CUSTOMER SIGNATURE		

HST: 10066 9050 RT0001

INTERNAL COPY